

Shirley Hiew (LKK Auto)

From: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Sent: Thursday, 10 September 2020 5:19 pm
To: SUR
Cc: Lim, Kok-Chong; Fong, Andy-SY
Subject: RE: Re: Alert - Adj Mandate Maintained - FBN9093A - Claim Handler: Azlan, Syazairdina

Hi,

Mandate approved exclusion remarks below to update.

Kindly advise repairer as scratches and not affected the bike performance like **Front Brake Disc Scratch, Front Brake ABS Disk, Front Brake Caliper, Radiator Assy, Coolant, Repair Left Fork - Not Require**

Thanks

Regards,
Thaddaeus Ng
AIG
Motor Claims Surveyor
Claims|AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Hp +(65) 8876 5433
Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, September 10, 2020 5:00 PM
To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Cc: sur@lkkauto.com
Subject: [EXTERNAL] Re: Alert - Adj Mandate Maintained - FBN9093A - Claim Handler: Azlan, Syazairdina

This message is from an external sender; be cautious with links and attachments.

This mail is associated with :
***FBN9093A (8247304017SG)**
OD
Aug 31 2020 11:00AM
[SITI NORKHAIRISHA BINTE KHAIRIL ANUAR]
Bike Production

Dear Thaddaeus,

We refer to your below email above matter.

At this point, we have removed these items, refer to IA.

Subsequently, upon dismantle, if these items found damage, we will re-seek mandate with photos.

Kindly let us have your authorize approval.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->
From: AIG_SG
To: LKK_HQ
Sent On: 09/09/2020 04:19 PM
Subject: Alert - Adj Mandate Maintained - FBN9093A - Claim Handler: Azlan, Syazairdina

Maintained:Mandate not approve for parts offer to revert to repairer. Front Brake Disc Scratch - To Reuse Front Brake

ABS Disk - Not Require Front Brake Caliper - To Reuse Radiator Assy - To Ruse Coolant - Not Require Repair Left Fork - Not R

This is an auto-generated email. Do not reply to this email.

Sent by : Hiew May Fung (LKK Auto Consultants Pte Ltd)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.