

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2020

ASSESSMENT FOR REPAIR: HONDA NC750XA - FBN9093A

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$345.00 / CRK
1 pc	• Front mudguard brace	\$145.00 ? - BT
1 pc	• Front wheel axle	\$135.00 x SVL
1 pc	• Front brake disk	\$335.00 ? - SCR
1 pc	• Front brake ABS disk	\$235.00 ? - SCR
1 pc	Front brake caliper	X SVC \$395.00 ? / SCR, NEC
2 pcs	• Steering stem bearing	\$90.00 SCR / SVL
1 pc	Front right fork assembly	\$1,085.00 SCR / SVL
1 pc	• Front left fork assembly	X SVC \$1,085.00 SCR ? X R
1 pc	Steering head crown	\$405.00 X SVL
1 pc	• Steering stem underbracket	\$440.00 SCR ? / DEF
1 set	Crash bar	BT / \$395.00 SCR ? / right
1 pc	Brake lever	SCR / \$105.00 SCR
1 pc	Right balancer	\$65.00 / SVL
1 pc	Right view mirror	\$145.00 / SCR
1 pc	• handle bar	\$245.00 x SVL ? - DEF
1 pc	Right front signal	\$165.00 / SCR
1 pc	Right body fairing	\$395.00 / SVL
1 pc	Honda wing decal	\$58.00 / NEC
1 set	• Right black cover	\$350.00 ? - CRK
1 pc	• Radiator assembly	\$655.00 ? - DEF
1 pc	Brake pedal	\$175.00 / SCR
1 pc	Right front footrest	\$85.00 / SVL
1 pc	Right front footrest holder	\$295.00 x SVL
1 pc	Right rear footrest	\$65.00 / SVL
1 pc	Exhaust heat shield	\$195.00 / SCR
1 pc	Exhaust assembly	\$950.00 / SCR
		\$9,038.00
		\$903.80
		\$8,134.20
	<u>Special nett items</u>	
1 pc	Front sport rim	\$750.00 / DMG
1 pc	• coolant	X SVC \$50.00 ? / NEC
1 pc	Box bracket	\$250.00 / DEF
1 pc	Top case	\$480.00 / MIS
1)	• Towing charges	\$100.00 / NN
2)	Replace, reallgn and adjust above damaged parts	\$800.00 300
		450

	Repair left fork	\$150
3)	Repair and balancing front wheel rim	\$90.00 40
4)	• To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00 100 100
5)	Reset Meter	\$120.00 NN
6)	To knock, straighten chassis & body balancing	\$450.00 NN
7)	Spray painting	\$300.00 100
	Total Estimate	<u><u>\$11,704.20</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

NAL LK
4/9/2020 1200
L/S

3 DAYS

CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: