



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. AC2004528
INV Date 24/06/2020
Reference CS3/III20006331/Esf3s2
Code III2



PROFESSIONAL SERVICE FEE

Vehicle No. SLN 8843R

Insured Veh. SHC 1042L

Claim No.

Policy No.

Accident Date 12/06/2020

Inspection Date 16/06/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 16.06.2020 02.33pm	
- Dismantle Inspection 17.06.2020 01.47pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd