LOD Re: Accident on 29/8/2020 involving SHD 6315L & GBF 1772T (China Taiping's insured) Our Ref: TAX/08/20/2078/lg

Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) < LeeGek@smrt.com.sg>

Mon 12/10/2020 4:59 PM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

1 attachments (641 KB)

0837\_001.pdf;

Dear All,

We quantify our own losses as follows:-

Cost of Repair	\$3,092.69					
Loss of Rental	\$343.47	(	3	days x	\$114.49	)
LTA search fee	\$7.00					
Total	\$3,443.16					

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) Police/GIA reports
- 4) Accident vehicle laid-up report
- 5) LTA search

Our hirer engaged his own lawyer to claim for his injury and loss of income.

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6556 3548)

Claims Department

SMRT Automotive Services Pte Ltd





Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

RECEIVED

07 OCT 2020

SMRT AUTOMOTIVE SERVICES PTE LTD
Claims & Insurance Agency

SMRT Automotive Services Pte Ltd 2 Tanjong Katong Road, Tower 3, Paya Lebar Quarter, #08-01, Singapore 437161 Tel: 65 69083530 Fax: 65 69083592

# Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV201000063
Date : 06.10.2020
Vehicle No. : SHD6315L

Your Ref No. : TAX/08/20/2078

Our Ref No. : 24108016

Description		Terms	30	: 30 Days	
	Qty Uni		(Discount)		Amount
Parts	Cos	t %	Amount	ō.	-200110
COVER, FR BUMPER COVER, FR BUMPER RH CLIPS PIECE, FRT & RR BUMPER GRILLE, RADIATOR GUPPORT, FR BUMPER RH ABSORBER, FR BUMPER REINFORCEMENT FRONT UPPER ABSORBER, FR BUMPER LOWER	1.00 \$ 495.5 0.00 \$ 28.1 0.00 \$ 1.5 0.00 \$ 165.0 0.00 \$ 76.9 0.00 \$ 70.3 0.00 \$ 691.1 0.00 \$ 117.00	0 (100.00) 0 0.00 0 0.00 0 0.00 0 0.00 0 0.00	\$ 495.50 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00	\$ \$ \$ \$ \$ \$ \$ \$ \$	0.00 0.00 0.00 0.00 0.00 0.00
EINFORCEMENT FRONT LOWER EXTENSION SUBASSY, RH  AMP ASSY, FOG, RH  OVER ASSY, ENGINE  OOD SUB-ASSY  NSULATOR, HOOD  INGE ASSY, HOOD, LH  INGE ASSY, HOOD, RH  ABLE ASSY, HOOD  JPPORT, RADIATOR UPPER RH  NIT, HEADLAMP, RH  ENDER SUB-ASSY, FR, RH  MBLEM, SIDE PANEL (HYBRID)  FAL SUB-ASSY, RH  NER, FR FENDER, RH  EEL, DISC FRONT  RE	0.00 \$ 238.50 0.00 \$ 116.30 0.00 \$ 910.20 0.00 \$ 180.10 0.00 \$ 938.40 0.00 \$ 393.90 0.00 \$ 57.00 0.00 \$ 57.00 0.00 \$ 57.00 0.00 \$ 76.70 1.00 \$2558.90 1.00 \$ 933.10 1.00 \$ 52.90 0.00 \$ 50.20 0.00 \$ 198.40 0.00 \$ 1555.10 0.00 \$ 126.74	0.00 0.00 0.00 0.00 0.00 0.00 0.00	\$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00 \$ 255.89 \$ 933.10 \$ 13.22 \$ 0.00 \$ 0.00 \$ 0.00	* * * * * * * * * * * * * * * * * * * *	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 2303.01 0.00 39.68 0.00 0.00

Payment Instructions

Please issue chaque in favour of 8MRT TAXIS PTELTD.

Koo Yew Chung Koo Yew Chung (Oct 6, 2020 15:35 GMT+8)

Authorised Signature for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

SMRT Automotive Services Pte Ltd 2 Tanjong Katong Road, Tower 3, Paya Lebar Quarter, #08-01, Singapore 437161 Tel: 65 69083530 Fax: 65 69083592

# Tax Invoice

GST Reg No. : MR-8500001-7

: 199004280Z

Invoice No. : IV201000063

Date

: 06.10.2020

Vehicle No. : SHD6315L

Our Ref No. : 24108016

Your Ref No. : TAX/08/20/2078

Terms

Description			Terms		: 30 Days		
	Qty		Add	/ (Di	scount)		Amount
WIPER WASHER JAR	0.00	\$ 183.60	0.00		mount		
COVER ASSY, ENGINE	1.00	\$ 180.10	(100.00 <u>)</u>		0.00	\$ \$	0.00
Labour			3	ub-To	tal	\$	2342.69
TO REPAIR FRONT PORTION	1.00	\$ 300.00	0.00	\$	0.00	\$	300.00
Others						·	500.00
TO REPSRAY FRONT BUMPER TO REPSRAY FRONT HOOD	1.00	\$ 200.00	0.00	\$	0.00	\$	200.00
O RESPRAY FRONT SUPPORT PANEL	0.00	\$ 378.00 \$ 180.00	0.00	\$	0.00	\$	0.00
CO RESPRAY RIM CO RESPRAY FRONT FENDER RH	0.00	\$ 180.00	0.00	\$ \$	0.00 0.00	\$ \$	0.00
O CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 200.00 \$ 20.00	0.00 0.00	\$	0.00	\$	200.00
O APPLY RUST-PROOFING ON AFFECTED REA	1.00	\$ 30.00	0.00	\$ \$	0.00	\$ \$	20.00
O DO WHEEL ALIGNMENT / TYRE ALANCING	0.00	\$ 120.00	0.00	\$	0.00	\$	30.00
O REMOVE AND REFIT TYRE RIM SPRAYING PURPOSE)	0.00	\$ 120.00	0.00	\$	0.00	\$	0.00
O REMOVE AND REFIT WIRE HARDESS O REPLACE SUNDRY PARTS		\$ 200.00 \$ 100.00	0.00	\$	0.00	\$	0.00
WASH AND VACUUM	0.00		0.00	\$	0.00	\$	0.00
			0.00	\$	0.00	\$	0.00
			GRAND	TOTAL	\$	3	3,092.69

Remark :

Make/Model : PRIUS4

Accident Date : 29.08.2020

Payment Instructions

Please issue chique in favour Of SMRT TAXIS PTE LTD.

Koo Yew Chung (Oct 6, 2020 15:35 GMT+8)

Authorised Signature for SMRT Automotive Services Pte Ltd

E. & O.E



### **SMRT Taxis Pte Ltd**

### **MEMORANDUM**

To:

Claims Dept

Our Ref:

TAX/08/20/2078

From:

SMRT Taxis Pte Ltd

Date:

10/9/2020

# ACCIDENT ON 29/08/2020 INVOLVING SHD 6315L & GBF 1772T ALONG YISHUN AVENUE 6

This is to confirm that the daily rental rate for SHD 6315L is \$114.49 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you,

Yours sincerely SMRT TAXIS PTE LTD

for Manager



## **Laid Up Report**

Accident Start Date: 20/08/2020

Accident End Date : 03/09/2020

Date Generated: 03/09/2020

User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/08/20/2078	SHD6315L	SMRT Taxis Pte Ltd	TOYOTA	PRIUS4	24108016	31/08/2020 11:01 AM	03/09/2020 11:07 AM

## A Şingapore Government Agency Website

### Enquire Transaction History

Transattion History Details

Log Date/Time:

31 Aug 2020 / 14:55:56

Asset Type: Asset ID: Transaction Type:

User ID:

Vehicle

GBF1772T

18.32 Insurance Enquiry (GIRO Payment)

ESASBAHO - BALQISH BINTE ABDUL HALIL

Transaction Amount:

\$7.49

Channel:

Business Transaction Reference No.:

External Agency

20200831145556247202

Search Date / Time:

29 Aug 2020 12:07:00

Insurance Company:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time,

**Enquire Related Logs** 

Back to List