

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: EQ	DATE	: 3/9/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLC8786E		
VEHICLE MODEL	: HONDA VEZEL		Xiao Tony
CHASSIS NO	: RU11110513		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAIVER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehid</i>	1	\$ 880.00	\$ 880.00
2	REAR BUMPER SIDE HOLDER LH <i>Na</i>	1	\$ 23.50	\$ 23.50
3	REAR BUMPER SIDE REFLECTOR LH <i>crubd</i>	1	\$ 141.10	\$ 141.10
4	REAR BUMPER SIDE GARNISH LH <i>Dehid</i>	1	\$ 195.00	\$ 195.00
5	REAR FENDER LH <i>Dehid</i>	1	\$ 884.40	\$ 884.40
6	REAR FENDER ARC PROTECTOR LH <i>yt</i>	1	\$ 196.00	\$ 196.00
7	REAR FENDER INNER SHIELD LH <i>Dehid</i>	1	\$ 147.50	\$ 147.50
8	REAR FENDER AIR VENT LH <i>Dehid</i>	1	\$ 48.90	\$ 48.90
9	TAILLAMP <i>crubd</i>	1	\$ 474.60	\$ 474.60
10	ROCKER PANEL OUTER SKIRTING LH <i>Dehid</i>	1	\$ 685.00	\$ 685.00
11	REAR AXLE <i>Best</i>	1	\$ 1,513.20	\$ 1,513.20
12	REAR WHEEL HUB C/W BEARING <i>Dehid</i>	1	\$ 335.00	\$ 335.00
13	REAR SHOCK ABSORBER LH <i>Best</i>	1	\$ 330.70	\$ 330.70

TOTAL PRICE: \$ 5,854.90

LESS 20% \$ ~~1,170.98~~ 1170.98

SUB TOTAL PRICE: \$ ~~2,442.28~~ 4683.92

4921.60
3937.28

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Na</i>	1 SET	\$ 50.00	\$ 50.00
2	REAR FENDER ARC PROTECTOR CLIPS LH <i>Na</i>	1 SET	\$ 30.00	\$ 30.00
3	REAR FENDER INNER SHIELD CLIPS LH <i>Na</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR DOOR PROTECTIVE FILM STICKER LH <i>Na</i>	1	\$ 60.00	\$ 60.00
5	ROCKER PANEL OUTER SKIRTING CLIPS LH <i>Na</i>	1 SET	\$ 50.00	\$ 50.00

30
20
20
40
30

6	REAR WHEEL RIM LH <i>lat</i>	1	\$ 680.00	\$ -680.00	<i>480</i>
7	REAR TYRE LH <i>torn</i>	1	\$ 280.00	\$ -280.00	<i>*200</i>
			TOTAL :	\$ 1,180.00	

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TUFF COAT	\$ 150.00	<i>40</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE UPHOLSTERY	\$ 150.00	<i>40</i>	
7	TO REMOVE REAR UNDERCARRIAGE	\$ 380.00	<i>300</i>	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>	
		TOTAL:	\$ 2,780.00	

ESTIMATE REPORT

TOTAL PARTS COST: \$ *586392*
 TOTAL LABOUR COST: \$ 2,780.00
 TOTAL REPAIR COST: \$ *864392*

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 649728

4/s: 5.2k.

05 Days

(5.2k)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: