

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS3/AIG20007275/Eqf3s2-1		
78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120		Date: 14-09-2020			
ATTN	ATTN: JEFFREY NG		Code: AIG		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLN 8507L	Veh. Inspected	SMC 7362P	
	Policy No.	2100509474	Coverage (\$)	0.00	
	Claim No.	0923290103SG	Excess (\$)	0.00	
	Assign From	JEFFREY NG	Assign Date	05/09/2020	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. X3	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WBATR120X0LC94222	Colour	BROWN	
	Odometer	57919	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/50 R19	BRIDGESTONE	4 mm	
	L/H Front Tyre	245/50 R19	BRIDGESTONE	4 mm	
	R/H Rear Tyre	245/50 R19	BRIDGESTONE	4 mm	
	L/H Rear Tyre	245/50 R19	BRIDGESTONE	4 mm	
4.	I. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/07/2020	Inspection Date	14/07/2020	
	Survey held at	SAFE AUTO			
		1 KAKI BUKIT AVE 6 #01-52 AUTOBAY KAKI BUKIT SINGAPORE 417883			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: