



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/09/2020



User ID : PohSuan

Section A - Accident Details

Registration Number	SHD6139D
Case Reference Number	TAX/08/20/2083
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	PEH CHENG HUAT
Type of Accident	Side Swipe
Accident Date and Time	28/8/2020 6:53 PM
Accident Reported Date and Time	31/8/2020 4:31 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108042
Special Instruction to ARC, if any	RIGHT PORTION DAMAGE
Prepared Date and Time	2/9/2020 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$2,052.00	\$600.00
Total Spare Part Cost	\$5,657.78	\$932.26
Total Other Cost	\$1,140.00	\$110.00
TOTAL COST	\$9,694.78 \$11,407.64	\$2,042.26 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	02/09/2020 3:56 PM	03/09/2020 3:10 PM
Signature		
Remarks		P/P, Before paint photo.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/09/2020

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0221	Invoice Number	
Quotation Date	16.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00 ✓

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
RESPRAY WHEEL CAP	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,052.00	\$600.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,140.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,300.70	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X
		67003-47211	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,294.90	100.00	\$0.00	Replace	Repair ✓
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	0.00	\$594.80	0.00	\$0.00	Replace	Not Given X
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$871.50	25.00	\$653.63	Replace	Replace ✓
		65637-47060	LINER, REAR FENDER, RH	0.00	\$139.80	0.00	\$0.00	Replace	Not Given X

} SVC

Nec

SVC

Cru

SVC



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/09/2020

User ID : PohSuan

			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$211.50	25.00	\$158.63	Replace	Replace	X	Scr
		4261147450	WHEEL, DISC	0.00	\$1,879.40	0.00	\$0.00	Replace	Not Given	X	SVC
		52591-47080	SEAL, RR BUMPER, RH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X	SVC
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	100.00	\$0.00	Replace	Repair	2	
		52462-47020	PAD, RR BUMPER, RH & LH, 1	0.00	\$4.00	0.00	\$0.00	Replace	Not Given	X	SVC
		52462-47030	PAD, RR BUMPER, RH & LH, 2	0.00	\$4.00	0.00	\$0.00	Replace	Not Given	X	SVC
		52402-47130	PAD, RR BUMPER, RH & LH, 3	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	X	SVC
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Not Given	X	SVC
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given	X	SVC
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.50	0.00	\$0.00	Replace	Not Given	X	SVC
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace		Nec
Total					\$7,370.64		\$932.26				

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total										

932.26 / 11,407.64#
+ 400.00 /
+ 710.00 /
2042.26 /

P/P
\$ 2,042.26
3 days