



Venda Engineering & Trading Pte Ltd

Quotation

From : VENDA ENGINEERING & TRADING PTE LTD 8 TUAS AVENUE 18 SINGAPORE 638892 Officer in Charge : SOON TAT NG Tel : Email :	Customer : GOLDBELL LEASING PTE LTD 59 SENOKO ROAD SINGAPORE 758123 Attn : Tel : 6494 2800 Fax No. : 6861 7097
--	--

Quotation No. : CQO20-0910013	Quotation Date : 04/09/2020	Terms : 30 DAYS
Vehicle No. : YP1555D	Chassis No. : FM65FMA30027	Policy Number :
Model : FUSO FM65FM2RDEB		Date of Accident :
Third Party Insurer :		TP Vehicle No. :
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
	YP1555D			
1	FRT BUMPER <i>lt</i>	1	1,125.1900	1,125.19
2	FRT RIGHT HEADLAMP <i>cm</i>	1	1,002.3200	1,002.32
3	FRT RIGHT FOG LAMP <i>cm</i>	1	293.2500	293.25
4	FRT RIGHT HEADLAMP RIM <i>cm</i>	1	302.7300	302.73
5	FRT RIGHT CORNER PANEL <i>cm</i>	1	1,183.6300	1,183.63
6	FRT CORNER PANEL SIGNAL LAMP <i>scd</i>	1	211.9100	211.91
7	FRT RIGHT DOOR <i>repair X</i>	1	3,323.8600	3,323.86
8	FRT RIGHT STAP GARNISH <i>cm</i>	1	267.8400	267.84
9	LESS25%	1	-1,927.6800	-1,927.68
10	REMOVE & RENEW FRT BUMPER,CORNER PANEL,RIGHT DOOR , STEP GARNISH,HEADLAMP, SIGNALLMAP	1	1,400.0000 <i>600</i>	1,400.00
11	TRANSFER DOOR PARTS	1	120.0000 <i>X</i>	120.00
12	PUTTY & SPRAY PAINT RENEW PARTS	1	1,000.0000 <i>700</i>	1,000.00

C/F 0.00

Page 1 of 2

Mailing Address : No.1, Sunview Road, #08-15 Eco-Tech@Sunview, Singapore 627615
 Contact Number (HQ) : (Tel) : 6355 9014 (Purchasing Dept) 6355 9015 (Sales Dept.)
 (Fax) : 6254 0424
 E-mail : venda_eng@singnet.com.sg

bizSAFE



IDAC Accident Report

Consistent? : Yes or No

U.O.A.

U.O.A.



Venda Engineering & Trading Pte Ltd

Quotation

From : VENDA ENGINEERING & TRADING PTE LTD 8 TUAS AVENUE 18 SINGAPORE 638892 Officer in Charge : SOON TAT NG Tel : Email :	Customer : GOLDBELL LEASING PTE LTD 59 SENOKO ROAD SINGAPORE 758123 Attn : Tel : 6494 2800 Fax No. : 6861 7097
---	---

Quotation No. : CQO20-0910013	Quotation Date : 04/09/2020	Terms : 30 DAYS
Vehicle No. : YP1555D	Chassis No. : FM65FMA30027	Policy Number :
Model : FUSO FM65FM2RDEB		Date of Accident :
Third Party Insurer :		TP Vehicle No. :
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Hp 90010068
6 days
48
07/07/2020 @ 1720
Resue after repair

Sub Total	8,303.05
Discount	(0.00)
GST(7.00%)	581.21
Total (SGD)	8,884.26

VENDA ENGINEERING & TRADING PTE LTD



Authorised Signature

Please conduct the survey at
Venda Engineering @ 8 Tuas Avenue 18 Level 5 Singapore 638892

We accept the above quotation.

Customer's Name & Signature
Company Stamp/Date