

Not Authorised
11 Day &
Recovery After Painting
6 days

ESTIMATE TO REPAIR

VEHICLE NO. : SDU 1750 D
MAKE : MERCEDES BENZ
MODEL : C 180 KOMPRESSOR
YEAR : 2012
CHASSIS NO : WDD2040452A741423

SURVEYOR NAME : *LKK* SEP 2020
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 5-Sep-20
DATE OF ACCIDENT : 4-Sep-20
THIRD PARTY REF : SKP 5287 S
THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			\$ Bu 1,370.00	✓
1 pc	rear bumper reinforcement		\$ 42.00	\$ 740.00	7
2 pcs	rear bumper retainer			\$ Bu 84.00	X
1 pc	rear bumper chrome moulding - centre			\$ Me 200.00	1
2 pcs	rear bumper chrome moulding - side		\$ 144.00	\$ Me 288.00	1
1 pc	rear end panel			\$ 1,380.00	7
1 pc	rear boot lid			\$ Bu 1,380.00	7
1 pc	rear boot lock			\$ 325.00	7
1 pc	rear boot star			\$ Me 50.00	1
1 pc	rear boot C180 emblem			\$ Me 90.00	1
1 pc	rear boot kompressor emblem			\$ Me 116.00	1
1 pc	front bumper			\$ 1,310.00	7
1 pc	front bumper reinforcement			\$ 380.00	7
1 pc	front bumper number plate grill		\$ 90.00	\$ Bu 145.00	X
2 pcs	front bumper retainer			\$ Bu 180.00	X
1 pc	front grille			\$ CM 750.00	7
1 pc	front grille inner bracket		\$ 1,100.00	\$ 28.00	7
2 pcs	head lamps			\$ 2,200.00	7
					\$ 11,016.00
					\$ 1,101.60
	Less 10%				\$ 9,914.40
1 set	rear bumper sensor	S.Nett		\$ Bu 400.00	✓
1 set	number plate	S.Nett		\$ Bu 80.00	✓
	To putty & spray paint			\$ 1,200.00	800
	To check front wiring & focus head lights			\$ 30.00	200
	To check rear wiring & water leakage			\$ 30.00	200
	To anti-rust			\$ 80.00	300
	Labour Charges			\$ 800.00	700
TG/VL	TOTAL				\$ 12,534.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64569127 Email: edmund@lmtm.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd