



QUOTATION

Customer :

NO. : 36681

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

*out of order
all
r/s \$1300
3 days
John the Attorney*

DATE : 04/09/2020
CLAIM NO. : 11607
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBK3722Z
MAKE/MODEL : YAM / TMAX 530 CVT

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	Balance handle	REPLACE	1.00	\$84.00	84.00 ✓
2	BOARD FOOTREST 2 P/N: 54000	REPLACE	1.00	\$179.20	179.20 ✓
3	BODY COWLING 2 RH P/N: 53999	REPLACE	1.00	\$127.40	127.40 ✓
4	BRACKET MUFFLER	REPLACE	1.00	\$21.00	21.00 ✓
5	DAMPER (BOARD FOOTREST 2) P/N: 45958	REPLACE	1.00	\$2.10	2.10 ✓
6	DAMPER 1 P/N: 54010	REPLACE	1.00	\$1.40	1.40 ✓
7	DAMPER 2 (BOARD FOOTREST 2) P/N: 45961	REPLACE	1.00	\$3.50	3.50 ✓
8	DAMPER 3 (BOARD FOOTREST 2) P/N: 45962	REPLACE	1.00	\$10.50	10.50 ✓
9	FENDER INNER 2 P/N: 46003	REPLACE	1.00	\$43.40	43.40 ✓
10	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$63.00	1,008.00 ✓
11	LEG SHIELD 1 P/N: 45967	REPLACE	1.00	\$233.80	233.80 ✓
12	LEVER 2 P/N: 54006	REPLACE	1.00	\$53.20	53.20 ✓
13	MOLE SIDE COVER 2 P/N: 45925	REPLACE	1.00	\$159.60	159.60 ✓

*36681 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price		Amount
14	PANLE INNER 4 P/N: 45970	REPLACE	1.00	\$12.60	one	12.60 ✓
15	PLATE 2 P/N: 45989	Replace	1.00	\$35.00	but	35.00 ✓
16	PROTECTOR MUFFLER P/N: 40084	REPLACE	1.00	\$177.66	cut	177.66 ✓
17	PROTECTOR MUFFLER (FRONT) P/N: 40085	REPLACE	1.00	\$152.88	cut	152.88 ✓
18	PROTECTOR MUFFLER (INNER) P/N: 40086	REPLACE	1.00	\$52.36	tw	52.36 ✓
19	STAND MAIN P/N: 53751	REPLACE	1.00	\$177.80	n	177.80 ✓
SUB TOTAL						\$2,535.40
GST @ 7 %						\$177.48
GRAND TOTAL (SGD)						\$2,712.88

50% deposit required before ordering of parts.

Validity: 30 days

2640.40

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

454.6
152

*36681 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

NO. : 37372

Supplementary 1 To QTN: 36681

DATE : 19/12/2020
CLAIM NO. : 11607
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBK3722Z
MAKE/MODEL : YAM / TMAX 530 CVT

S/N	Description	Action	Qty	Unit Price	Amount
1	MIRROR REAR VIEW RH ASSY P/N: 54011	Replace	1.00	\$105.00	scr 105.00
SUB TOTAL					\$105.00
GST @ 7 %					\$7.35
GRAND TOTAL (SGD)					\$112.35

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*37372 *

