

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI20009589/Ksf3e2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date: 28-09-2020 Code: UOI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GW 5267K	Veh. Inspected	SHD 5385R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	M11D10772009	Excess (\$)	0.00	
	Assign From	KATIE LEE	Assign Date	08/09/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS (A)	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JTDKB3FU903078922	Colour	M. P. WHITE / RED	
	Odometer	207026	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	SAILUN	9 mm	
	L/H Front Tyre	195/65 R15	SAILUN	9 mm	
	R/H Rear Tyre	195/65 R15	SAILUN	9 mm	
	L/H Rear Tyre	195/65 R15	SAILUN	9 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.					
	Accident Date	03/09/2020	Inspection Date	08/09/2020	
	Survey held at TRANS-CAB AUTO SERVICES PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				