



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20009592/Atf3e2

73 BRAS BASAH ROAD

Date: 09-10-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : SERENE LIM

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 506C	Veh. Inspected	SMJ 8791R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1102229-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	08/09/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 520i	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBAXG12040DX52299	Colour	BLACK
Odometer	122325 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	CONTINENTAL	6 mm
L/H Front Tyre	245/45 R18	CONTINENTAL	6 mm
R/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm
L/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/09/2020	Inspect Date / Time	08/09/2020 (01:40 PM)
Survey held at	8 KAKI BUKIT AVE 4 #08-46		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------