

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 22 Sep 2020

## **Preliminary Advice**

Insured Vehicle No	: GBD5282A	Accident Date	: 04/09/2020
TP Vehicle No	: SMH6424A	Assignment Date	: 08/09/2020
Make	: NISSAN NOTE	Est. Duration of Repair	: 6
Date of Inspection	: 09/09/2020		
Inspection At	: TC AUTOCLINIC PTE LTD (LENG KEE) 25 LENG KEE ROAD SINGAPORE 159097		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,053.52
Revised Amount	:S\$	4,518.52
Check Items (Estimated)	:S\$	1,862.00
Total	:S\$	6,380.52
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conduct without "prejudice" basis.