



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20009620/R1yf3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 18-09-2020



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 6014E	Veh. Inspected	SLS 2307K
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003883	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	08/09/2020

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF 1.4 TSI AT	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WVWZZZAUZHW126630	Colour	GREY
Odometer	41463	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40Z R18	PIRELLI	6 mm
L/H Front Tyre	225/40Z R18	PIRELLI	6 mm
R/H Rear Tyre	225/40Z R18	PIRELLI	6 mm
L/H Rear Tyre	225/40Z R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/09/2020	Inspection Date	09/09/2020
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------