

Shiau Chan (LKKAuto)

From: Wai Yin Ng <waiyin.ng@transcab.com.sg>
Sent: Monday, 14 September 2020 10:13 AM
To: Shiau Chan (LKKAuto)
Cc: Claims
Subject: RE: TP VEHICLE SHC 5566R DOA: 05/09/2020 -- AAD2009-036
Attachments: SHC5566R EST.PDF

[Without prejudice](#)

Dear Shiau Chan

Amount confirmed \$4,700 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Friday, 11 September, 2020 3:56 PM
To: Wai Yin Ng <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHC 5566R DOA: 05/09/2020

Dear Wai Yin,

Based on our surveyor's marking estimate, the calculation of repair cost will be at Lump Sum \$4,700.00 before GST and 5 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)