



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI20009632/Gqf3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-12-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3016U	Veh. Inspected	SFJ 6922B
Policy No.		Coverage (\$)	0.00
Claim No.	D20003600MFSH	Excess (\$)	0.00
Assign From	CHRIS LIM	Assign Date	09/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALPHARD 2.5	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	AGH300140585	Colour	WHITE
Odometer	18159	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	235/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	235/50 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	235/50 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/08/2020	Inspection Date	09/09/2020
Survey held at	LYE DESIGNS 10, AMK AUTOPOINT, 04-04 ANG MO KIO IND PARK 2A, SINGAPORE 568047		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------