

**RE: Fire inspection report SKB 7080G**

Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Thu 24/9/2020 5:03 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>

Dear Sherwin

Please proceed and amend as spoken.

To bill \$500/-

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>

**Sent:** Wednesday, 16 September 2020 3:27 PM

**To:** Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

**Subject:** Fire inspection report SKB 7080G

Hello Byran

Above attached is the completed fire investigation report for SKB 7080G, need you to check through before submitting to insurance.

Best Regards,

**Sherwin Beh | Technical Investigator**

**LKK Auto Consultants**

Office: 6256 3561 | Email: [SherwinBeh@lkkauto.com](mailto:SherwinBeh@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)