

Quotation of repair scania new bus no: 101.PL1200.20315

Parts replacement

Structure

1. Front structure assembly.	1 UT	\$4007
2. Rhs structure assembly.	1 UT	\$481
3. Roof structure assembly.	1 UT	\$707
4. Front wall sealing plate assembly.	1 UT	\$134
5. Insulation of front seal plate.	1UT	\$96
6. Windsshield wipers installation assembly.	1UT	\$1218
7. Front wall reinforcement assembly.	1 UT	\$242
8. Body reinforcement plate & roof front connect (6pcs).	1UT	\$60

Door

1. Passenger door panel assembly.	1UT	\$1221
2. Out-swing door installation assembly.	1UT	\$1905

Glass & Others

1. Front windshield installation assembly.	1UT	\$5074
2. Window glass above driver window.	1UT	\$1228
3. Driver window assembly.	1UT	\$1635
4. Window glass below driver window.	1UT	\$890
5. RF oblique window glass.	1UT	\$1639
6. RF triangle glass.	1UT	\$890



Reg. No. 199407022Z GST Reg. No. 199407022-Z
Office Address : 31 GUL CIRCLE SINGAPORE 629569
Tel : 68626011 (3 Lines) Fax : 68626022
Email : snl@snl.com.sg

7. Window glass on the passenger door.	1UT	\$1214
8. Window glass under the passenger door.	1UT	\$794
9. Weather bar.	1UT	\$41
9. Air instak assembly.	1UT	\$170
10. Cutter channel.	2UT	\$214

Fiberglass

1. Front external revetment assembly.	1UT	\$1534
2. Dashboard install assembly(RH).	1UT	\$2603
3. Dashboard panel install assembly.	1UT	\$336
4. Internal revertment between window(part)	1UT	\$529
5. Side window curtain assembly.	1UT	\$10
6. External decoration parts assembly(RH).	1UT	\$873
7. Front grill assembly.	1UT	\$824
8. Sealants.	20UT	\$500

External lamps assembly

1. Front Headlamp(RH).	1UT	\$593
2. Floor marker lamp.	1UT	\$47
3. Front middle outline marker lamp.	1UT	\$334
4. Reflector (RH).	1UT	\$72

Electrical Cables & Other

1. Front step install assembly.	1UT	\$593
---------------------------------	-----	-------



Reg. No. 199407022Z GST Reg. No. 199407022-Z

Office Address : 31 GUL CIRCLE SINGAPORE 629569

Tel : 68626011 (3 Lines) Fax : 68626022

Email : snl@snl.com.sg

2. Floor cover & maintence cap assembly(parts)	1UT	\$660
3. Front internal revertment assembly.	1UT	\$908
4. Heating defroster installation assembly.	1UT	\$644
5. Cable 11M/16M BNC/RCA Video.	1UT	\$86
6. Microphone cable.	1UT	\$98
7. Roof Harness.	1UT	\$863
8. Dashboard Harness.	1UT	\$440
9. Dashboard lower harness.	1UT	\$1084
10. Amplifier cable.	1UT	\$157
11. 5M BNC/RCA cable.	1UT	\$43
12. 10M/1M/20M/15M camera cable.	1UT	\$183
13. Antenna.	1UT	\$61
14. Air conditioner panel cable.	1UT	\$180

Total amount before gst **\$37,615**



順納隆物流私人有限公司
SNL LOGISTICS PTE LTD

Reg. No. 199407022Z GST Reg. No. 199407022-Z
Office Address : 31 GUL CIRCLE SINGAPORE 629569
Tel : 68626011 (3 Lines) Fax : 68626022
Email : snl@snl.com.sg

Labour

To supply labour to dismantle, cut & remove all the damaged & attached items to facilitate the repair and welding new structures, patch fiberglass, installation of news cables, adjust all parts alignments, complete with install for the above items.

\$17,000

to supply labour and material to based cause, apply putty, grind and spray paint the front areas, RH side areas, complete with clear coat.

\$3,000

Final total amount before gst

\$57,615