



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG19022122/Qyf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 18-09-2020



ATTN : KATHLYN CHEOK

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 9043Y	Veh. Inspected	SLJ 6457G
Policy No.	1800073282	Coverage (\$)	0.00
Claim No.	5731039988SG	Excess (\$)	0.00
Assign From	Kathlyn Cheok	Assign Date	09/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104562395	Colour	BLUE
Odometer	57144	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	4 mm
L/H Front Tyre	215/45 R17	MICHELIN	4 mm
R/H Rear Tyre	215/45 R17	MICHELIN	4 mm
L/H Rear Tyre	215/45 R17	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2019	Inspection Date	17/12/2019
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------