

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Thursday, 29 October 2020 10:54 AM  
**To:** Dhanya B.Purushothaman  
**Cc:** Admin A  
**Subject:** RE: III Ref: MCT20090111 // LKK Ref: LKK Ref:CC4/III20009668/pa3 [ACCIDENT INVOLVING SH 7744Z(III) AND SKT 6949M ON 08/09/2020]  
**Attachments:** Email from 3rd Party dd 281020.pdf

Hi Dhanya,

We refer to the above matter.

We were informed by third party repairer that their client will be selling off their vehicle and they will not be pursuing the case further.

In view of this, we will proceed to close case at our end.

Please note that no bill to III as no survey done by LKK.

Thanks.

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | Fax: 6741 4108

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Tuesday, 15 September 2020 10:07 AM  
**To:** Dhanya B.Purushothaman <Dhanya@iii.com.sg>  
**Subject:** III Ref: MCT20090111 // LKK Ref: LKK Ref:CC4/III20009668/pa3 [ACCIDENT INVOLVING SH 7744Z(III) AND SKT 6949M ON 08/09/2020]

Hi Dhanya,

Attached is a copy of video from third party for your easy reference.

Based on third party video, third party was turning into the 2<sup>nd</sup> lane from the right and there is a jerk. It is likely that our driver encroached into third party lane and resulted the collision.

Kindly upload insured video in Merimen for our review. Thanks.

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | Fax: 6741 4108

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)