



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 48236

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0642/2020/NS
Date : 8-Sep-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
4 days - ok - Jy - 01 Dec 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ng Kok Yee
Address : 52 Punggol Walk
#05-05
Singapore 828831
Telephone : Hp +65 83160169
Type of Claim : Own Damage Claims
Policy No. : 1900000759
Vehicle No : **SMH 1201 J**
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Jan-19
Engine No : CHZ A91797
Chassis No : WAUZZZGA0KA000753
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Sep-20
Place of Accident : Junction Of Punggol Way And Punggol Central

Telefax

Estimated Labour Charges for Accident Vehicle SMH 1201 J

S/N Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 280.00	\$ 280.00
2	To remove and transfer rhs headlight control unit and power module.	S/N	\$ 400.00	
3	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,400.00	\$ 1,000.00
4	To respray front bumper, bonnet and hinges.		\$ 2,500.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,772.00	\$ 2,572.00

Telefax

Material List for Accident Vehicle Regn No. SMH 1201 J

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,854.00	\$ 1,482.00
2	FRONT BUMPER FIXING PARTS	\$ 343.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 195.00	
4	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 167.00	\$ 133.60
5	FRONT BUMPER END CAP - RH	\$ 34.00	
6	FRONT BUMPER SPOILER	\$ 296.00	
7	FRONT BUMPER CLOSING ELEMENT	\$ 154.00	
8	WHEEL SPOILER - RH	\$ 34.00	
9	RADIATOR GRILLE	\$ 1,395.00	\$ 1,116.00
10	RADIATOR GRILLE STRIKER PLATE	\$ 123.00	
11	FRONT BUMPER FOAM FILLER PIECE	\$ 77.00	\$ 61.20
12	FRONT BUMPER CARRIER	\$ 679.00	\$ 543.20
13	FRONT BUMPER COVER	\$ 99.00	
14	CAUTION SIGN STICKER	NEC \$ 14.00	
15	AIRCON STICKER	NEC \$ 8.00	
16	BONNET	\$ 2,757.00	\$ 2,205.60
17	BONNET ATTACHMENT PARTS	\$ 163.00	
18	BONNET LID HINGE - LH / RH	2 \$ 122.00	
19	BONNET STRIKER - LH / RH	2 \$ 218.00	
20	BONNET SOUND ABSORBER	\$ 217.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 8,949.00	\$ 5,541.60

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1201 J

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 5,541.60
21	BONNET IMPACT PROTECTION - CENTRE / LH / RH		\$ 90.00	\$ 70.48
22	BONNET LID LOCK	2	\$ 423.00	
23	BONNET BOWDEN CABLE - CENTRE		\$ 57.00	
24	BONNET RELEASE ELEMENT		\$ 57.00	
25	BONNET RELEASE LEVER		\$ 13.00	
26	HEADLIGHT MOUNTING - RH		\$ 117.00	
27	LED HEADLIGHT - RH		\$ 4,859.00	
28	LIFT CYLINDER - RH		\$ 141.00	
29	RADIATOR AIR GUIDE - RH		\$ 30.00	
30	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 22.00	\$ 17.04
31	EXTERNAL TEMPERATURE SENSOR		\$ 56.00	
32	FRONT WHEEL COVER - LH / RH	2	\$ 636.00	\$ 508.80
33	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
34	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS CHARGES			\$ 15,810.00	\$ 6,197.92
TOTAL LABOUR CHARGES			\$ 5,772.00	\$ 2,572.00
GRAND TOTAL			\$ 21,582.00	\$ 8,769.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant