

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	Ubi Road 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0631/2020/TT
DATE	:	9-Sep-20
WIP	:	47821

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 0689877

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR LEEWAI MENG (LI WEIMING)
ADDRESS	:	BLK 187 BUKIT BATOK WEST AVENUE 6 #10-51 SINGAPORE 650187
TELEPHONE	:	HP +65 96259384
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070006071
VEHICLE NO	:	SMJ 8296 D
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR	:	21/1/2020
ENGINE NO	:	CVK 087120
CHASSIS NO	:	WAUZZZF46KA11270
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	2-Sep-20
PLACE OF ACCIDENT	:	PIE AFTER BKE EXIT (TUAS)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 8296 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N	\$ 360.00 ✓	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR	S/N	\$ 280.00 ✓	✓
3	TO DISMANTLE AND RENEW REAR BUMPER, REAR BUMPER SPOILER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 2,100.00 1000 ✓	✓
4	TO RESPRAY REAR BUMPER, REAR LID AND HINGES. ✓ ✓ ✗		\$ 2,200.00 1100 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 5,132.00</u></u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 8296 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>reld</i>		\$ 2,698.00	✓	2158.40
2 REAR BUMPER FIXING PARTS <i>new</i>		\$ 454.00	+	
3 REAR BUMPER SECURING STRIP <i>? Nec</i>		\$ 220.00	? ✓	176
4 REAR BUMPER SPOILER <i>reld</i>		\$ 246.00	✓	196.40
5 REAR BUMPER TRIM <i>could</i>		\$ 289.00	✓	230.80
6 REAR BUMPER BRACKET - LH/RH <i>?</i>	2	\$ 230.00	? X	NN
7 REAR LGHT REFLECTOR - LH/RH <i>new</i>	2	\$ 82.00	+	
8 REAR BUMPER CARRIER <i>? Dented</i>		\$ 1,002.00	? ✓	801.60
9 REAR BUMPER CARRIER SEAL <i>? Nec</i>	2	\$ 28.00	? ✓	22.08
10 REAR BUMPER GUIDE SECTION - LH / RH <i>? new</i>	2	\$ 44.00	+	
11 REAR BUMPER HOLDING STRAP - LH / RH <i>new</i>	2	\$ 164.00	+	
12 REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	TBC	+	
13 REAR PARKING AID SEAL RING <i>new</i>	4	\$ 14.00	+	
14 BOOT LID CONTROL UNIT <i>new</i>		\$ 399.00	+	
15 REAR LID <i>Dented</i>		\$ 2,623.00	✓	2098.40
16 REAR LID HINGE - LH / RH <i>? new</i>	2	\$ 452.00	+	
17 REAR LID LOCK <i>new</i>		\$ 227.00	+	
18 REAR LID ATTACHEMENT PARTS <i>new</i>		\$ 144.00	+	
19 REAR LID LOCK STRIKER <i>? new</i>		\$ 33.00	+	
20 REAR LID FLAP GASKET <i>new</i>		\$ 203.00	+	
SUB TOTAL SPARE PARTS	:	\$ 9,552.00		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 8296 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 PACKING ADHESIVE		\$ 18.00	✓	14.40
22 AUDI EMBLEM		\$ 122.00	✓	97.60
23 A4 INSCRIPTION		\$ 95.00	✓	75.36
24 REAR CROSS PANEL TRIM		\$ 164.00	+	
25 REAR NUMBER PLATE	S/N	\$ 60.00	✓	✓
26 SUNDRIES		\$ 300.00	?	2.24 ✓ NEC
TOTAL SPARE PARTS	:	\$ 10,311.00		
TOTAL LABOUR CHARGES	:	\$ 5,132.00		
GRAND TOTAL	:	\$ 15,443.00		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *17/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT