

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0631/2020/NS 5-Oct-20 Glory Tan 1 of 1 SMJ 8296 D Audi A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
Labours			
1	To repair rear end panelling.	\$ 700.00	250
2	To respray rear end panelling.	\$ 900.00	550
TOTAL		\$ 1,600.00	

For Premium Automobiles Pte Ltd

Adrian Lj

05/10/20

Add 1 day
fls

Authorised Signature

Car-in 5/10/2020 WIP: 47821

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Kiam/Hong

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 8296 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>Rehd</i>		\$	2,698.00	✓
2 REAR BUMPER FIXING PARTS <i>new</i>		\$	454.00	+
3 REAR BUMPER SECURING STRIP <i>?</i>		\$	220.00	?
4 REAR BUMPER SPOILER <i>Rehd</i>		\$	246.00	✓
5 REAR BUMPER TRIM <i>Carhd</i>		\$	289.00	✓
6 REAR BUMPER BRACKET - LH/RH <i>?</i>	2	\$	230.00	?
7 REAR LGHT REFLECTOR - LH/RH <i>new</i>	2	\$	82.00	+
8 REAR BUMPER CARRIER <i>Dented</i>		\$	1,002.00	2 ✓
9 REAR BUMPER CARRIER SEAL <i>?</i>	2	\$	28.00	?
10 REAR BUMPER GUIDE SECTION - LH / RH <i>free</i>	2	\$	44.00	+
11 REAR BUMPER HOLDING STRAP - LH / RH <i>free</i>	2	\$	164.00	+
12 REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2		TBC	+
13 REAR PARKING AID SEAL RING <i>new</i>	4	\$	14.00	+
14 BOOT LID CONTROL UNIT <i>new</i>		\$	399.00	T
15 REAR LID <i>Dented</i>		\$	2,623.00	✓
16 REAR LID HINGE - LH / RH <i>free</i>	2	\$	452.00	+
17 REAR LID LOCK <i>free</i>		\$	227.00	+
18 REAR LID ATTACHEMENT PARTS <i>new</i>		\$	144.00	+
19 REAR LID LOCK STRIKER <i>free</i>		\$	33.00	+
20 REAR LID FLAP GASKET <i>free</i>		\$	203.00	+
SUB TOTAL SPARE PARTS	:	\$	9,552.00	

Adrian Li
05/10/20
HKS

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.