

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 14 Sep 2020

## **Preliminary Advice**

Insured Vehicle No	: SKA5696Z	Accident Date	: 10/09/2020
TP Vehicle No	: SHD5661T	Assignment Date	: 11/09/2020
Make	: TOYOTA VIOS	Est. Duration of Repair	: 2
Date of Inspection	: 11/09/2020		
Inspection At	: TRANSCAB (HQ) NO 2 AMK STREET 63 SINGAPORE 569111		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,675.55
Revised Amount	:S\$	1,409.18
Check Items (Estimated)	:S\$	342.30
Total	:S\$	1,751.48

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on WP