

Kennerh

ASSIGNMENT

From:

Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

Days of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555

Estimate No: MC1901396
 Date: 11 Sep 2020
 Policy No: D19MYPV01015726
 Veh Reg No: SJL5903E
 Make/Model: HONDA CIVIC 1.8L 5AT

ATTN: Motor Claim Department
 Your Ref No: SJL5903E
 Claim Type: Own Damage
 Accident Date: 10/09/2020

*Not Authorized
 61 Sing &
 Recovery After Paint*

Estimate Repair Cost to Vehicle No : SJL5903E

12 days

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
SPARE PARTS				
1 FRONT WINDSCREEN		1 PC <i>CM</i>	450.00	✓
2 FRONT WINDSCREEN MOULDING TOP		1 PC <i>MC</i>	30.00	✓
3 FRONT WINDSCREEN MOULDING SIDE - CHECK PRICE		2 PC	0.0000	?
4 FRONT BONNET		1 PC <i>B</i>	300.00	✓
5 FRONT BONNET HINGE LH & RH	<i>MSPD Return</i>	2 PC	60.00	✓
6 FRONT BONNET INSULATOR		1 PC	40.00	✓
7 FRONT BONNET INSULATOR CLIPS		10 PC <i>MC</i>	80.00	✓
8 FRONT BONNET RUBBER SIDE (SMALL) SIDE		2 PC <i>CM</i>	12.00	✓
9 FRONT BONNET RUBBER INNER		1 PC <i>CM</i>	10.00	✓
10 FRONT BONNET INNER LOCK		1 PC <i>B</i>	45.00	✓
11 FRONT BONNET CABLE		1 PC <i>T</i>	30.00	✓
12 HEADLAMP LH & RH		2 PC <i>CM</i>	500.00	✓
13 HEADLAMP LOWER BEAM LH & RH		2 PC <i>B</i>	36.00	✓
14 HEADLAMP HID BULD LH & RH	<i>olsa oljmt</i>	2 PC	360.00	✓
15 HEADLAMP HID CONTROL UNIT LH & RH		2 PC	440.00	✓
16 FRONT GRILLE		1 PC <i>MC</i>	60.00	✓
17 FRONT GRILLE EMBLEM		1 PC <i>MC</i>	15.00	✓
18 FRONT GRILLE CHROME MOULDING		1 PC <i>MC</i>	60.00	✓
19 FRONT GRILLE CLIPS		8 PC <i>MC</i>	8.00	✓
20 FRONT BUMPER		1 PC <i>B</i>	180.00	✓
21 FRONT BUMPER SIDE RETAINER LH & RH	<i>olsa</i>	2 PC <i>MC</i>	20.00	✓
22 FRONT BUMPER CLIPS		15 PC <i>MC</i>	15.00	✓
23 FRONT BUMPER REINFORCEMENT		1 PC <i>B</i>	155.00	✓
24 FOGLAMP LH & RH	<i>olsa</i>	2 PC	400.00	✓
25 FRONT FENDER LH & RH	<i>olsa</i>	2 PC	310.00	✓
26 FRONT FENDER COWLING LH & RH	<i>olsa</i>	2 PC	96.00	✓
27 FRONT FENDER COWLING CLIPS		16 PC <i>MC</i>	16.00	✓
28 FRONT FENDER TOP COVER LH & RH		2 PC <i>MC</i>	30.00	✓
29 RADIATOR SUPPORT PANEL		1 PC <i>B</i>	340.00	✓
30 RADIATOR SUPPORT PANEL TOP GARNISH		1 PC <i>MC</i>	35.00	✓
31 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS		8 PC <i>MC</i>	8.00	✓
32 AIR CON CONDENSER		1 PC <i>B</i>	350.00	✓
33 AIR CON CONDENSER FAN MOTOR		1 PC <i>T</i>	95.00	✓
34 AIR CON CONDENSER FAN BLADE		1 PC <i>MC</i>	30.00	✓
35 AIR CON CONDENSER FAN COWLING		1 PC <i>CM</i>	65.00	✓
36 AIR CON CONDENSER PIPE (COND-COMP)		1 PC	110.00	?
37 AIR CON CONDENSER PIPE (COND-VALVE)		1 PC	90.00	?
38 AIR CON CONDENSER PIPE (COMP-VALVE)		1 PC	75.00	?
39 AIR CON CONDENSER TOP BRACKET LH & RH		2 PC <i>MC</i>	30.00	✓
40 AIR CON CONDENSER BOTTOM BUSH LH & RH		2 PC <i>T</i>	20.00	✓



BTL CM

olsa

olsa

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
41 RADIATOR ASSY		1 PC	360.00	✓
42 RADIATOR FAN MOTOR		1 PC	95.00	?
43 RADIATOR FAN BLADE		1 PC	40.00	?
44 RADIATOR FAN COWLING		1 PC	65.00	✓
45 RADIATOR TOP HOSE		1 PC	12.00	✓
46 RADIATOR BOTTOM HOSE		1 PC	12.00	?
47 RADIATOR TOP BRACKET LH & RH		2 PC	30.00	✓
48 RADIATOR TOP BUSH LH & RH		2 PC	16.00	✓
49 RADIATOR BOTTOM BUSH LH & RH		2 PC	20.00	?
50 RADIATOR SPARE TANK		1 PC	22.00	?
51 RADIATOR SPARE TANK HOSE (SMALL)		1 PC	18.00	?
52 RADIATOR CAP BRACKET		1 PC	35.00	X
53 WIPER WASHER TANK		1 PC	50.00	✓
54 WIPER WASHER TANK NECK		1 PC	15.00	X
55 WIPER WASHER TANK MOTOR		1 PC	35.00	X
56 ABS PUMP		1 PC	980.00	?
57 ALTERNATOR		1 PC	480.00	?
58 ALTERNATOR BELT		1 PC	45.00	?
59 INTAKE HEATSHIELD TOP - CHECK PRICE		1 PC	0.0000	?
60 INTAKE HEATSHIELD LOWER - CHECK PRICE		1 PC	0.0000	?
61 AIR DUCT OUTER		1 PC	35.00	✓
62 AIR FILTER BOX TOP		1 PC	25.00	X
63 AIR FILTER BOX LOWER		1 PC	35.00	?
64 BATTERY COVER		1 PC	10.00	?
65 BATTERY TRAY		1 PC	15.00	?
66 BATTERY LOWER BRACKET		1 PC	35.00	X
67 ENGINE ECU		1 PC	1,637.70	?
68 ENGINE UNDER COVER		1 PC	45.00	X
69 ENGINE UNDER COVER CLIPS		10 PC	10.00	X
70 ENGINE MOUNTING TOP		1 PC	70.00	?
71 ENGINE MOUNTING RH		1 PC	135.00	?
72 ENGINE MOUNTING REAR		1 PC	70.00	?
73 GEARBOX MOUNTING LH		1 PC	90.00	?
74 FRONT HWEELHOUSE PANEL RH		1 PC	250.00	✓
75 AIRBAG SENSOR		2 PC	170.00	✓
76 AIRBAG ECU		1 PC	460.00	✓
77 DASHBOARD ASSY		1 PC	480.00	✓
78 DASHBOARD AIRBAG LH		1 PC	650.00	✓
79 DASHBOARD AIRBAG COVER LH		1 PC	200.00	✓
80 STEERING WHEEL AIR BAG		1 PC	750.00	✓
81 STEERING WHEEL AIR BAG CONTACT RING		1 PC	351.20	✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

SURVEYOR COPY

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
82 FRONT SEAT BELT LH & RH		<i>2m</i> 2 PC	<u>S\$</u> 660.00	<u>S\$</u> ✓
			13,519.90	
	Add 10%		1,351.99	14,871.89
Special Nett				
83 NUMBER PLATE		1 PC	<i>B</i> 35.00	✓
84 RADIATOR COOLANT		1 PC	<i>na</i> 30.00	✓
85 POWER STEERING FLUID		1 PC	<i>na</i> 50.00	✓
86 INNER SEAL		1 PC	<i>na</i> 20.00	✓
87 WINDSCREEN SEALANT		1 PC	<i>na</i> 40.00	✓
88 BATTERY		1 PC	180.00	7
				355.00
LABOUR				
89 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	<i>30d</i>
90 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	✓
91 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	<i>60d</i>
92 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1 PC	120.00	✓
93 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.		1 PC	280.00	<i>25d</i>
94 TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG, PASSENGER AIR-BAG, SEATBELTS AND AIR-BAG CONTROL BOX.		1 PC	150.00	✓
95 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	250.00	✓
96 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, FRT WHEELHOUSE PANEL RH. TO KNOCK & REPAIR FRT WHEELHOUSE PANEL LH, FRT CHASSIS LH & RH, FRT DOOR LH & RH, FRT DOOR PILLAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,600.00	<i>110d</i>
97 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR LH & RH, FRT DOOR PILLAR LH & RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE LH & RH.		1 PC	1,600.00	<i>128d</i>
				4,220.00



Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

825H

Vehicle Details

Vehicle No.:

SJL5903E

Vehicle to be Exported:

No

Intended Deregistration Date:

10 Sep 2020

Vehicle Make:

HONDA

Vehicle Model:

HONDA CIVIC 1.8L 5AT

Primary Colour:

Brown

Manufacturing Year:

2008

Engine No.:

R18A14009508

Chassis No.:

JHMFD16309S201622

Maximum Power Output:

103.0 kW (138 bhp)

Open Market Value:

\$25,978.00

Original Registration Date:

03 Dec 2008

First Registration Date:

03 Dec 2008

Transfer Count:

1

Actual ARF Paid:

\$25,978.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

02 Dec 2023

COE Category:

B - Car (1601cc & above)

COE Period(Years):

5

PQP Paid:

\$15,777.00

COE Rebate Amount:

\$10,184.00

Total Rebate Amount:

\$10,184.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/09/2020 11:40
Date Of Accident 10/09/2020 09:15
Exact Location Of Accident CTE TOWARDS CITY NEAR AMK AVE 5
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJL5903E
Insured/Policyholder
Name Of Registered Owner LEE HAI HOCK
NRIC No SXXXX825H
Email Address ALSON_LEE@EMCRESOURCES.COM.SG
Mobile Phone No (LOCAL) +65-93844688
Alternative Phone No OTHERS-93844688

Vehicle Particulars

Manufacturer HONDA
Model CIVIC-1.8 L 5AT (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category PRIVATE CAR


Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number D19MTPV01015726
Cover Note Number 03/12/2019 - 02/12/2020

Driver

Name of Driver LEE HAI HOCK
NRIC No SXXXX825H
Date Of Birth 16/04/1967
Occupation INDOOR
Date Of Driving Pass 23/01/1988
Driving Experience 32 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-93844688
Fax Number
Contact Number OTHERS-93844688
EMail Address ALSON_LEE@EMCRESOURCES.COM.SG

Date of accident: 10/10/2020 Time: 9.16 AM Location: CTE tenant city near AMK Ave 5
 My Vehicle A: STL 5903E Vehicle B: TAXI Vehicle C: _____



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 9.15am, I drive at the speed of 80-90km/h along CTE, the moment of start to rick my eyes and looks somewhere else, notice that the Taxi in front of me brake but I hv no time to react to stop my brake and knock against the taxi tail and my car still go on. I tried to stop the car but car still moving on thus I drove to the right to let the car stop slowly in moment and lastly stop.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address :
 & myself : alson_lee@emoresources.com.sg
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personel's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY