



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0646/2020/NS
DATE	:	9-Sep-20
WIP	:	48271

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR LIM ENG KIAT
ADDRESS	:	34 LUCKY VIEW SINGAPORE 467466
TELEPHONE	:	HP +65 81258616
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900066968
VEHICLE NO	:	SFZ 8300 Z
MODEL CODE	:	AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR	:	25/3/2019
ENGINE NO	:	DAX 049909
CHASSIS NO	:	WAUZZZF5K2018545
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Aug-20
PLACE OF ACCIDENT	:	VELOCITY MALL CARPARK RAMP

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFZ 8300 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 2,400.00 500	✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH WHEEL ARCH TRIMS.	S/N \$ 4,000.00 1750	$ \begin{aligned} &350 \times 2 = 1100 \\ &\text{spoiler} = 250 \\ &\text{Arch trim} \times 2 = 200 \times 2 \\ &= 400 \\ &\hline &1750 \end{aligned} $
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 7,472.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFZ 8300 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Rebond</i>		\$ 2,595.00	✓	✓ 2075.60
2	REAR BUMPER FIXING PARTS <i>neu</i>		\$ 267.00	✗	
3	FRONT BUMPER CLOSING ELEMENT - LH <i>neu</i>		\$ 111.00	✗	
4	FRONT BUMPER GRILLE - CENTRE <i>neu</i>		\$ 142.00	✗	
5	FRONT SPOILER <i>neu Reps</i>		\$ 754.00	✗	
6	FRONT BUMPER UNDERRUN BAR <i>neu</i>		\$ 474.00	✗	
7	FRONT BUMPER CLOSING ELEMENT <i>neu</i>		\$ 171.00	✗	
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>lit</i>		\$ 574.00	✓	✓ 458.80
9	FRONT BUMPER END CAP - LH <i>neu</i>		\$ 91.00	✗	
10	FRONT BUMPER SECURING STRIP - LH <i>neu</i>		\$ 37.00	✗	
11	FRONT BUMPER GUIDE SECTION - LH <i>neu</i>		\$ 38.00	✗	
12	FRONT FENDER - LH <i>Reps</i>		\$ 1,411.00	✗	
13	FRONT FENDER ATTACHMENT PARTS <i>2</i>		\$ 66.00	✗	
14	FRONT FENDER BRACKET - LH		\$ 17.00	✗	
15	FRONT FENDER BRACE - LH		\$ 222.00	✗	
16	WHEEL HOUSING LINER - LH <i>neu</i>		\$ 275.00	✗	
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>neu</i>		\$ 38.00	✗	
18	WHEEL SPOILER - LH <i>lit</i>		\$ 159.00	✓	✓ 126.8
19	HEADLIGHT MOUNTING - LH <i>neu</i>		\$ 117.00	✗	
20	LED HEADLIGHT - LH <i>lit</i>		\$ 7,931.00	✓	✓ 6344.8
21	LIFT CYLINDER - LH <i>neu</i>		\$ 138.00	✗	
22	FRONT WHEEL COVER - LH / RH <i>LH ut, RH neu</i>		\$ 1,250.00	✓	✓ 1000
23	SUNDRIES <i>?</i>		\$ <i>nec</i> 250.00	✓	✓ 29.36
TOTAL SPARE PARTS			\$ 17,128.00		
TOTAL LABOUR CHARGES			\$ 7,472.00		
GRAND TOTAL			\$ 24,600.00		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Lj
11/09/20

Not Authorised, 04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT