



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20007109/R1vf3e2-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 23-09-2020



Code : III2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8154B	Veh. Inspected	SBS 8929U
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20070057	Excess (\$)	0.00
Assign From	DHANYA	Assign Date	08/07/2020

#### 2. Vehicle Particulars & Condition

Make & Model	SCANIA KUB4X2 9.3L A	c.c	9290
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	YS2K4X20001865092	Colour	MULTI COLOUR
Odometer	874196	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	05/07/2020	Inspection Date	08/07/2020
Survey held at	SBS TRANSIT LTD (Branch) 28 SOON LEE ROAD SINGAPORE 628083		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------