

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

| 1. GENERAL INFORMATION | | |
|--|---|--|
| INCIDENT NO. : /20200903/0704 | LOCATION OF FIRE: | |
| FIRE REPORTED ON: 03 September 2020 | Multi-Storey Car Park (MSCP) | |
| TIME OF CALL: 18:07:58 hrs | Block 509A, Woodlands Drive 14, Singapore 731509 | |
| STATION COVERAGE: Woodlands Fire Station | | |

2. INCIDENT INFORMATION

FIRE INVOLVED: A section of the dashboard (behind the glove compartment) of a Honda Vezel (SKW451E).

METHOD OF EXTINGUISHMENT: By a member of public using an internal hose reel jet before the arrival of SCDF crew.

PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the wirings / connections)

DAMAGE SUSTAINED: As a result of the fire, the section of the dashboard comprising electrical cables and components were damaged. The glove compartment and other parts in the area sustained varying degrees of heat and smoke damage. The interior of the car sustained water damage.

3. FATALITY/INJURY INFORMATION

| NAME | PIN/FIN | | DEAD/INJURIES SUSTAINED |
|------|---------|-----|----------------------------|
| NIL | NIL | NIL | NIL |

REPORT CERTIFIED TRUE AND CORRECT BY:

CINDY HAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated Fire Report. No signature is required.