

SMV2288D

aler

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



11 SEP 2020

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

#car in #

Estimate No. : b1 55989
Date Estimated : 11/09/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leu Teck Soon
245 Simei St 5
#04-48

Singapore 520245

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV2288D	WBAJR12080BR79829	28/08/2020	520i	0

DESCRIPTION**VALUE**

To replace including to knock out dented area caused by the accident

850 1,275.00

To respray front bumper

934 1,038.00

To remove and install front right side view cameras including program and conduct checks for proper function.

226 ? 266.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries

? 80.00

Total Labour 1: 2,836.00

DESCRIPTION**QTY****PRIC****VALUE**

C CLIP FOR PLASTIC NUT ?

14

1.10

15.40

COVER GRILLE RH (m)

1

76.25

76.25

GRILLE AIR INLET MIDDLE (LINES) ?

1

99.80

99.80

RH GRILLE AIR INLET OPEN (LINES) (m) ?

1

116.45

116.45

RH PROTECTIVE STRIP LINES (LUXURY) ?

1

68.80

68.80

FRT IMPACT ABSORBER BOTTOM ?

1

63.00

63.00

RH BUMPER GUIDE ?

1

16.95

16.95

RH BUMPER GUIDE ?

1

16.95

16.95

FRT BUMPER PANEL PRIMED (PMA de

1

1,377.95

1,377.95

EXPANDING RIVET D=8MM ?

10

1.10

11.00

FRT RH WHEEL ARCH FRT SECTION COVER at

1

132.70

132.70

ENGINE COMPARTMENT SHIELDING FRT ?

1

171.95

171.95

RH COVER BOTTOM ?

1

71.20

71.20

RH FOG LIGHT LED (BLENDE BLACK) ?

1

471.40

471.40

DECOUPING RING PDC TORQUE CONVERTER nec

2

5.10

10.20

ULTRASONIC SENSOR MINERALWEISS(WA96 mis

1

370.00

370.00

Total Parts : 3,090.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55989
Date Estimated : 11/09/2020
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV2288D	WBAJR12080BR79829	28/08/2020	520i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No	Claim No.
Dated Time 14/09/2020 @ 1630	Excess S\$
Surveyor's Name Ryan	Sign
Surveyor's Tel 900 16068	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail	
No. of Working Days Recommend 3 days	



Labour 1	:	2,836.00
Parts	:	3,090.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	414.82
Grand Total	:	6,340.82

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Est. Repairs: _____ days
Val.: Yes or No

Survey held at _____