

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 21 Sep 2020

Preliminary Advice

Insured Vehicle No : GBG1818R
TP Vehicle No : SMT2460H
Make : TOYOTA NOAH HYBRID
Date of Inspection : 18/09/2020
Inspection At : BW WORKSHOP SERVICES PTE LTD (HQ)
291 KAKI BUKIT AVENUE 1, SHUN LI INDUSTRIAL PARK
SINGAPORE 416080
Accident Date : 12/09/2020
Assignment Date : 15/09/2020
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,852.50
Revised Amount	:S\$	2,678.44
Check Items (Estimated)	:S\$	2,381.40
Total	:S\$	5,059.84

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : survey on 'wp'