

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Date: 15<sup>th</sup> September 2020 Your Ref: D20003036MFSH

Our Ref: CS1/FCI20009887/Dss2

## M/s MS First Capital Insurance Ltd

36 Robinson Road #16-01 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## **EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YN 4215B** INSURED VEHICLE: SHA 1458G ACCIDENT DATE: 30/07/2020

We thank you for your instruction on 15/09/2020.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : YN 4215B

Make & Model : Isuzu NPR85UH5AKC

Year of Registration : 2013
Chassis Number : JAANPR85HD700349
Engine Capacity : 2999cc

Engine Capacity : 2999cc

Vehicle sustain extensive damage at front portion, repair cost exceed nett value.



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Market Value S\$ 30,000.00 (inclusive of fridge)

Less: LTA Reimbursement Value (RV) (S\$ 20,847.00)

Nett Liability S\$ 9,153.00

========

Vehicle Inspected By:



ANG BRYAN TANI Automotive Assessor / Investigator



K.K.LAU CPT (RET)

BEng(Hons),B.Bus,MBA,PEng(UK),PE(USA),

MASME(USA), MInstAEA(UK), MIRTE,MCIArb

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.