

ARM SUB-ASSY, REAR BUMPER, LH	NH	1	\$139.60	\$139.60	X
REAR TRUNK LOWER W/S MOULDING	NH	1	\$180.80	\$180.80	X
REAR BUMPER REVERSE SENSOR	Dem	1	SN \$135.70	\$135.70	X
TAIL LAMP ASSY (UPPER)	o/s broken N/S NH	2	\$557.90	\$1,115.80	X
TAIL LAMP ASSY (LOWER)	o/s broken N/S NH	2	\$548.40	\$1,096.80	X
TAIL LAMP QUARTER PANEL	o/s Bnc N/S NH	2	\$216.00	\$432.00	X
TAIL LAMP SIDE COVER	Wade o/s N/S NH	2	\$256.00	\$512.00	X
REAR TAILLAMP GUIDE - WHITE	NH	2	\$95.30	\$190.60	X
REAR END PANEL	Bnc	1	\$602.10	\$602.10	X
REAR END PANEL GARNISH	broken	1	\$161.80	\$161.80	X
REAR WIRING ASSY	socket broken	1	\$582.40	\$582.40	X
REAR SPARE TYRE PANEL	Bnc	1	\$667.70	\$667.70	X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Wt	1	\$101.40	\$101.40	X
REAR FIBER TOOL BOX TRIM (LH/RH)	broken	2	\$598.00	\$1,196.00	X
REAR FIBER TOOL BOX CENTER	NH	1	\$186.20	\$186.20	X
SPARE TYRE LOCK NUT	Wt	1	\$88.40	\$88.40	X
SPARE TYRE LOCK NUT BRACKET	Wt Wt	1	\$113.50	\$113.50	X
SPARE TYRE SIDE PANEL (LH/RH)	NH	2	\$196.50	\$393.00	X
REAR EXHAUST PIPE	Dent	1	\$1,163.40	\$1,163.40	X
REAR EXHAUST PIPE HANGER	NH	1	\$40.70	\$40.70	X
REAR EXHAUST PIPE INSULATOR	Wt	1	\$314.60	\$314.60	X
REAR EXHAUST PIPE CENTRE INSULATOR	NH	1	\$498.60	\$498.60	X
REAR FENDER, RH	Bnc	1	\$836.70	\$836.70	X
REAR FENDER, LH	Wt	1	\$836.70	\$836.70	X
REAR FENDER INNER PANEL (LH/RH)	NH	1	\$728.00	\$728.00	X
REAR FENDER OUTER PANEL, RH	Dent	1	\$486.00	\$486.00	X
REAR FENDER PANEL, ROOF SIDE OUTER, RH	Dem	1	\$311.00	\$311.00	X
REAR FENDER REINFORCEMENT, ROCKER PANEL, RH	NH	1	\$552.30	\$552.30	X
REAR FLOOR PANEL SIDE (RH)	Bnc	1	\$276.20	\$276.20	X
REAR FENDER SHIELD (RH)	Wt broken	1	\$174.20	\$174.20	X
REAR FENDER TRIMBOARD (RH)	Wt	1	\$725.00	\$725.00	X
REAR FENDER TOP COVER (BLACK COLOR)(RH)	broken	1	\$301.10	\$301.10	X
REAR FENDER AIR DUCT	deformed	1	\$165.10	\$165.10	X
REAR CHASSIS MEMBER	Wt	1	\$1,180.80	\$1,180.80	X
REAR FLOOR PANEL SIDE (LH)	NH	1	\$717.60	\$717.60	X
REAR FLOOR PANEL SIDE (RH)	NH	1	\$717.60	\$717.60	X
REAR FLOOR BOARD ((RH)	NH	1	\$823.40	\$823.40	X
REAR FLOOR UNDER COVER (RH)	deformed	1	\$846.80	\$846.80	X
REAR CROSSMEMBER UNDER COVER	NH	1	\$891.10	\$891.10	X
REAR FLOOR PANEL	NH	1	\$2,850.50	\$2,850.50	X
REAR WINDSCREEN GLASS W/ MOULDING	deformed	1	\$1,778.30	\$1,778.30	X
REAR WINDSCREEN SEALANT	NH	1	\$46.00	\$46.00	X
PANEL SUB-ASSY, REAR DOOR, RH	Wt	1	\$1,258.30	\$1,258.30	X
REAR DOOR TRIMBOARD	NH	1	\$725.00	\$725.00	X
MOTOR, POWER WINDOW REGULATOR FRT, RH	NH	1	\$941.80	\$941.80	X
LOCK ASSY, BACK DOOR	NH	1	\$444.10	\$444.10	X
SUB TOTAL				\$43,655.00	
LESS 20% 25%				\$8,731.00	
DISCOUNTED TOTAL				\$34,924.00	
REVERSE CAMERA ASSY	SN	1	\$380.00	\$380.00	X

REAR LOWER W/S SEALANT <i>NH</i>	SN	1	\$46.00	\$46.00	X
REAR WINDSCREEN MOULDING <i>NH</i>	SN	1	\$160.00	\$160.00	X
REAR WINDSCREEN SEALANT <i>NH</i>	SN	1	\$46.00	\$46.00	X
REAR NO. PLATE WITH COVER <i>15T</i>	SN	1	\$45.00	\$45.00	✓
REAR TRUNK LID APPS STICKER <i>Hec</i>	SN	1	\$40.00	\$40.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>Hec</i>	SN	1	\$60.00	\$60.00	✓
REAR BUMPER RUBBER MAT <i>obtained</i>	SN	1	\$50.00	\$50.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH/RH) <i>Hec</i>	SN	2	\$100.00	\$200.00	✓
REAR DOOR COMFORT & APPS STICKER <i>NH</i>	SN	1	\$80.00	\$80.00	X
REAR DOOR ADVERTISEMENT LOGO <i>Hec</i>	SN	1	\$100.00	\$100.00	✓
SUB TOTAL				\$1,207.00	
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	1200
Spray Painting Charge		1	\$1,200.00	\$1,200.00	1000
Wiring Charge		1	\$140.00	\$140.00	30
Tuff Kote		1	\$160.00	\$160.00	40
Towing Charge		1	\$80.00	\$80.00	NH
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$120.00	80
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40
Re-set Rear ABS System		1	\$400.00	\$400.00	NH
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	60
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	NH
Re-set Rear Power Window System		1	\$200.00	\$200.00	NH
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150
TOTAL LABOUR				\$4,680.00	
ESTIMATE TOTAL				\$40,811.00	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

15/09/2020 @ 1730hrs
 NA Auction
 1/15mm 14 days.

[Signature]

LKK Auto

[Signature]

Provide BV before finalization.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 17-Sep-20

INSURANCE: 111

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 1369 E (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID LOCK <i>Damaged repaired</i>	1	\$457.90	\$457.90
ROOF TOP SIDE COVER - BLACK (LH/RH) <i>broken (distorted)</i>	2	\$956.30	\$1,912.60
REAR BUMPER UNDER CENTER COVER <i>distorted</i>	1	\$232.00	\$232.00
ROOF TOP LINING <i>1st crumpler</i>	1	\$2,059.50	\$2,059.50
REAR CROSS MEMBER <i>Dented 1st</i>	1	\$2,200.40	\$2,200.40
REAR FENDER TOP COVER (BLACK COLOR)(RH) <i>cut /</i>	1	\$301.10	\$301.10
SUB TOTAL			\$7,163.50
LESS 20% 25%			\$1,432.70
DISCOUNTED TOTAL			\$5,730.80

X
✓
✓
✓
✓
✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1 year

2kk Auto



BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 2-Oct-20

INSURANCE: TII

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 1369 E (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FRONT CUSHION SEAT (RH) <i>1st Dem</i>	1	\$1,180.00	\$1,180.00
SUB TOTAL			\$1,180.00
LESS 20% <i>25%</i>			\$236.00
DISCOUNTED TOTAL			\$944.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

400/-
SR

02/10/2020 @ 1000hr

Net Amount

[Signature]

JKK Auto

[Signature]