

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
LONPAC INSURANCE BHD			Ref : CS/LPC20009896/Qqf3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date: 01-10-2020 Code: LPC2		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBA 8165B	Veh. Inspected	SGP 7362S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	20/20/20/VC06/023653	Excess (\$)	0.00	
	Assign From	KENNY LIM	Assign Date	15/09/2020	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN LATIO 1.5L	c.c	1498	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	JN1BAAC11Z0003134	Colour	GREY	
	Odometer	209464	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	HANKOOK	6 mm	
	L/H Front Tyre	185/65 R15	HANKOOK	6 mm	
	R/H Rear Tyre	185/65 R15	HANKOOK	6 mm	
	L/H Rear Tyre	185/65 R15	HANKOOK	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/09/2020	Inspection Date	16/09/2020	
	Survey held at	60 JALAN LAM HUAT #05-45 CA	ARROS CENTRE		
	Repairer	TECH CHOON AUTOMOTIVE PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				