

**TECH CHOON AUTOMOTIVE PTE. LTD.**

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869

TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg

Business Reg No : 200311178 N GST Reg No. 200311178N

ZHANG LI S6960934A
507A WELLINGTON CIRCLE #10-162
(SINGAPORE) 751507

Attention: Motor Claim Department

Contact: Hp 98296977

Estimate : ES000265

Date : 11/09/2020

Vehicle Num. : SGP73625

Make/Model : NISSAN LATIO C11

Chassis/Eng# : @ JN18AAC11Z0003134 @

Accident Date : 11/09/2020

Claim No. : AMJtins.T150.113525.20 (sj)

Reference :

Policy No. : V0106656 (GREAT EASTERN)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	LIST ITEMS		
2.	1 PC	BUMPER REAR / CR4		683.50 532
3.	1 PC	BUMPER RETAINER REAR LH / BR		48.60
4.	1 PC	BUMPER RETAINER REAR RH / BR		48.60
5.	1 PC	BUMPER REAR INNER SPONGE ? X SVC		68.50 X
6.	2 PC	BUMPER BRACKET REAR ? X SVC	105.00	210.00 X
7.	1 PC	BOOT LID / BR		891.10 790
8.	1 PC	BOOT LID HANDLE OUTER ? X SVC		275.60 X
9.	1 PC	BOOT LID BOARD INNER X SVC		181.90 X
10.	2 PC	BOOT LID HINGE / BT	386.90	773.80 148
11.	1 PC	REAR END PANEL X R		491.60 X
12.	1 PC	REAR ENG PANEL INNER GARNISH ? X SVC		485.00 X
13.	1 PC	TAILLAMP LH / SCR RH ? X SVC	195.00	390.00 195
14.	1 PC	BOOT LID LOCK / Tapp		168.20
15.	1 PC	BOOT LID CABLE X SVC		89.30 X
16.	1 PC	BOOT LID LOCK CATCH X SVC		68.00 X
17.	1 PC	BOOT LID EMBLEM / Mpc.		56.00 X
18.	1 PC	BOOT LID LOGO GROMMET / Nec.		53.00 X
19.		TOWING TO REPORT CENTRE & BACK TO WORKSHOP. X SVC.		160.00 X
List Total S\$:				5,149.70 1,995.80
NETT ITEMS :				
1	1 SET	REVERSE SENSOR SET / Short		450.00 200
2	1 PC	BOOT LID TOP SPLICER X SVC.		850.00

CONTINUE /



TECH CHOON AUTOMOTIVE PTE. LTD.

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869

TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg

Business Reg No : 200311178 N GST Reg No. 200311178N

ZHANG LI S686034A
507A WELLINGTON CIRCLE #10-162
(SINGAPORE) 751507

Attention : Motor Claim Department

Contact : Hp 98296977

Estimate : ES000265

Date : 11/09/2020

Vehicle Num. : SGP73626

Make/Model : NISSAN LATI C11

Chassis/Eng# : @ JN1BAAC11Z0003134 @

Accident Date : 11/09/2020

Claim No. : AM.Jins.T150.113525.20 (sj)

Reference :

Policy No. : V0106656 (GREAT EASTERN)

S/N	Quantity	Particular	Unit Price	Amount S\$
3	1 PC	BUMPER LOWER SKIRT <i>X500</i>		850.00
4	1 PC	NUMBER PLATE REAR <i>X500</i>		48.00
Nett Total S\$:				2,198.00

LABOUR :

(LABOUR CHARGES)

TO REPLACE REAR BODY PARTS, WELDING REAR ENG PANEL.

FITTING & ADJUSTMENT.

TO SPRAY PAINTING FOR AFFECTED PORTION.

TO REPLACE TAILLAMP, CHECK WIRING & LIGHTING.

TO SPRAY UNDERCOAT

Labour Total S\$:

5 days
Repair days - *4 days*

45

After pain photo

Sun Pin (Hk)

16/04/2020

TP without prejudice

sunpin @ 11kkauto.com

600 850.00

/ 850.00

50 165.00

1,965.00

1,500

SingDollars : Nine Thousand Two Hundred Twelve & Cents Seventy Only

E & O.E

Total S\$

9 212 70

for TECH CHOON AUTOMOTIVE PTE LTD

This is only an estimate based on our preliminary inspection and does not
may be required after the work has began.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey time which
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1,945.80
- 30%

P = 1,397.06
N = 200
L = 1,500

3,097.06
- 20%

2,477.65

** Limit
Repair*

45 \$2,300 @ 5 days