

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 65096584

TO	: FIRST CAPITAL	DATE	: 16/9/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKE7963T		
VEHICLE MODEL	: HYUNDAI ELANTRA		
CHASSIS NO	: KMHDH41CMCU479919		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	SIONG / 97864483	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR LH DOOR <i>2nd</i>	1	\$ 1,378.90	\$ 1,378.90
2	REAR LH DOOR WEATHERSTRIP <i>3rd</i>	1	\$ 181.00	\$ 181.00
3	REAR LH DOOR LOCK <i>1st</i>	1	\$ 191.50	\$ 191.50
4	REAR BUMPER <i>1st</i>	1	\$ 459.40	\$ 459.40

TOTAL PRICE: \$ 2,210.80
LESS 20% \$ 442.16
SUB TOTAL PRICE: \$ 1,768.64

1378.90
1103.12

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR LH DOOR LOWER CHROME MOULDING <i>wt</i>	1	\$ 120.00	\$ 120.00
2	REAR LH DOOR BLACK TAPE <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR LH DOOR VISOR <i>new</i>	1	\$ 100.00	\$ 100.00
4	REAR LH WHEEL RIM <i>new</i>	1	\$ 680.00	\$ 680.00
5	REAR FENDER INNER SHIELD CLIPS LH <i>new</i>	1 SET	\$ 50.00	\$ 50.00

TOTAL : \$ 50.00

150

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 500.00	300	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 900.00	400	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	40	
5	TO TRANSFER REAR DOOR FITTINGS	\$ 150.00	80	

6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	X	
---	----------------------------	-----------	---	--

TOTAL: \$ 1,900.00

850

ESTIMATE REPORT

TOTAL PARTS COST: \$ 1,818.64

TOTAL LABOUR COST: \$ 1,900.00

TOTAL REPAIR COST: \$ 3,718.64

total: 2143.12.

H/S: 17K.

03Days

APPROVED DETAILS

SURVEYOR:

FAX:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: