



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI20009898/Asf3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-09-2020



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4736J	Veh. Inspected	SKE 7963T
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003724MFSH	Excess (\$)	0.00
Assign From	CHRIS LIM	Assign Date	15/09/2020

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KMHDH41CMCU479919	Colour	WHITE
Odometer	320525	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40 R18	FALKEN	6 mm
L/H Front Tyre	235/40 R18	FALKEN	6 mm
R/H Rear Tyre	235/40 R18	FALKEN	6 mm
L/H Rear Tyre	235/40 R18	FALKEN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	13/09/2020	Inspection Date	16/09/2020
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

#### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**