



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI19000051/Dyd3e2-1

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 01-10-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 2993S	Veh. Inspected	FBG 6804Y
Policy No.	DMCVSN14397518044	Coverage (\$)	0.00
Claim No.	SNM19D200061C02/ONGCK	Excess (\$)	0.00
Assign From	ADELINE CHNG	Assign Date	15/09/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FJS400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JH2NF03979K000102	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R14	TIMSUN	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70 R13	TIMSUN	2 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/12/2018	Inspection Date	03/01/2019
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------