

Shirley Hiew (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Friday, 9 October 2020 4:05 pm
To: Shirley Hiew (LKK Auto)
Subject: Re: SJT 4243R DOA - 15/09/2020

Hi Shirley,

Audit check done for SJT4243R, found exhaust pipe is serviceable, I already told Sun Pin to talk to repairer.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 9 October 2020 3:03 PM
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: SJT 4243R DOA - 15/09/2020

Hi Simon,

Kindly check the TP report and let me know whether can I submit this report.

Documents uploaded in Views.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.