

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 21 Oct 2020

Preliminary Advice

Insured Vehicle No	: GBJ5508T		
TP Vehicle No	: SKF2611L	Accident Date	: 13/09/2020
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 16/09/2020
Date of Inspection	: 16/09/2020	Est. Duration of Repair	: 5
Inspection At	: FONG MOTORS - KAKI BUKIT (HQ) 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,983.70
Revised Amount	:S\$	3,122.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,122.50
Lump Sum Repair	:S\$	2,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on wp