



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20009947/Uqf3s2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 30-09-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 8767U	Veh. Inspected	SMP 196E
Policy No.		Coverage (\$)	0.00
Claim No.	C10007283	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	16/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS C (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTDKD3B3801001221	Colour	BLUE
Odometer	144956	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	KAPSEN	5 mm
L/H Front Tyre	185/60 R15	KAPSEN	5 mm
R/H Rear Tyre	185/60 R15	KAPSEN	5 mm
L/H Rear Tyre	185/60 R15	KAPSEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/09/2020	Inspection Date	17/09/2020
Survey held at	15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------