

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ AG120009947/Uzf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 15888

coe 4-3-2022 1955m

net 5112

26/9/2025 \$5100 confirmed with AH long CRed \$14729.75, 74%)

Date/Time, File Pass to?

☐

Preli. Report

1) 28/9 1955m

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

5100

TOTAL

Not Authorized
NAN

submit to insurance.

17/9/20

Page No. 1

VEHICLE NO. SMP196E

TOYOTA PRIUS

2/s \$5100

8 days. limited repair

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front bumper		DLS 1020.00	✓ 616.25
2	Front bumper LHS and RHS foglamp @\$450		SVC 900.00	X
2	Front bumper LHS and RHS foglamp cover @\$80		SVC 160.00	X
2	Front bumper LHS and RHS side lamp @\$320		11 640.00	X
1	Front LHS headlamp		CNE 870.00	725.10
1	Front LHS headlamp top panel		R 240.00	X
1	Front support panel		R 560.00	X
1	Front bonnet		Bent 950.00	✓ 925.10
2	Front RHS and LHS fender @\$680	455.10 x 2	Bent 1360.00	✓ 910.20
2	Front RHS and LHS fender inner splash shield @\$280	MS Torn	560.00	12C 188.20
2	RHS Front and Rear Door @\$960	MSA 0.5 m/tn	1920.00	12C
2	RHS Front and rear Door glass run channel rubber @\$92	11	184.00	X
2	RHS Front and rear Door black side tape @\$72	0.5 m/tn	144.00	12C 60.00
1	RHS Side sill (rocker panel)	R	798.00	X
1	RHS Rear fender	R	982.00	X
1	RHS Rear fender inner splash shield	11	238.00	X
1	Rear bumper	R	980.00	X
1	Rear bumper side retainer LHS	11	78.00	X
1	LHS Front shock adsorber	Bent	492.00	✓ 422.10
1	LHS Front wheel bearing	R	248.00	✓
2	RHS and LHS Front lower arm @\$340	R	680.00	✓
2	RHS Front and rear shock absorber @\$492	for 0.5 m/tn	984.00	12C 422.10
2	RHS Front and rear wheel bearing @\$248	for 0.5 m/tn	496.00	12C
2	Front RHS and LHS wheel hub	Bent	230.00	✓
2	Front RHS and LHS link bar	SVC	65.00	X
1	Front steering rack and pinion	SVC	2150.00	X
1	Front undercarriage crossmember	SVC	680.00	X
1	Rear axle	11	1250.00	X
			12599.00	
less 25%			3149.75	25%
			9449.25	
SPECIAL NETT ITEMS				
2	Front fender HYBIRD emblem @\$120		R 240.00	100
2	RHS Front and rear tyre @\$250		SVC 500.00	X
1	LHS Front tyre		SVC 250.00	X
2	RHS Front and rear sports rim @\$860		cur/bent 1720.00	500
1	LHS Front sport rim		cur/bent 860.00	250
2set	RHS front and rear door inner trim board clips		11 80.00	X
2set	RHS front and rear fender inner shield clips		11 80.00	X
2set	Front and rear bumper clips		for 10C 80.00	30
TOTAL PARTS			13259.25	

6635.25

VEHICLE NO. SMP196E TOYOTA PRIUS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	2800.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	2200.00	1600
3	To remove and refix RHS doors fittings and components	200.00	50
4	To remove and refix rear compartment fittings, garnish etc so as to facilitate repairs for rear fender	150.00	80
5	To remove and replace front undercarriage parts	250.00	✓
6	To remove and replace rear undercarriage parts	120.00	11 X
7	To remove and replace rear axle	150.00	11 X
8	To remove and replace front cross member	150.00	11 X
9	To conduct full computerised wheel alignment test	120.00	60
10	To remove and refix a/c condenser ,radiator and top up gas	150.00	11 X
11	To perform anti-rust treatment on affected areas	280.00	100
Labour Total :		6570.00	
TOTAL (PARTS & LABOUR):		19829.25	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-4976.28

S.V - 880.00

L - 2940.00

8796.28