



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO19016400/Qtf3e2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 18-09-2020



Code : SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLS 1698M	Veh. Inspected	SME 5581B
Policy No.	D19MTPV01012350	Coverage (\$)	0.00
Claim No.	CMTD1904360	Excess (\$)	0.00
Assign From	RUTH CHUA GEK TIANG	Assign Date	16/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH HYBRID 1.8X CVT	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZWR800327363	Colour	BLACK
Odometer	97817	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	AUFINE	5 mm
L/H Front Tyre	195/65 R15	AUFINE	5 mm
R/H Rear Tyre	195/65 R15	AUFINE	5 mm
L/H Rear Tyre	195/65 R15	AUFINE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/09/2019	Inspection Date	17/09/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------