

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0670/2020/NS
DATE : 16-Sep-20
WIP : 49707

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS LEE YEE PING
ADDRESS : 10A BRADDELL ROAD
#20-02
SINGAPORE 579720
TELEPHONE : HP +65 96824994
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2000002554
VEHICLE NO : **SMR 6727 Z**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 17/1/2020
ENGINE NO : CZD 886648
CHASSIS NO : WAUZZZF30L1018349
MILEAGE : 7085KM
DATE IN : 16-Sep-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Sep-20
PLACE OF ACCIDENT : 8 MENG SUAN ROAD S779211

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 6727 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00 ✓	\$480/F
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00 ✗	\$250/F
3	TO DISMANTLE AND REINSTALL RH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL WIND MIRROR ASSY.	S/N	\$ 280.00 ✓	\$280/F
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 3,200.00	1000. \$1000/F
SUB TOTAL LABOUR CHARGES			: \$ 4,360.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 6727 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. ✓ ✓		\$ 3,400.00	1650 \$1650.00
6	TO RENEW RHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 280.00	X.
7	TO REAPPLY PAINT COATING ON DAMAGED AREA.	S/N	\$ 800.00 600	\$600.00
8	TO REAPPLY HEADLIGHT STICKER.	S/N	TBC	\$300.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$192.00
TOTAL LABOUR CHARGES			: <u>\$ 9,032.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 6727 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Distorted</i>		\$	2,045.00 ✓	\$1634.80
2 FRONT BUMPER CLOSING ELEMENT - RH <i>X NN</i>		\$	58.00 ?	
3 FRONT BUMPER GRILLE - RH <i>xen</i>		\$	109.00 X	
4 FRONT BUMPER CLOSING ELEMENT not <i>X NN</i>		\$	188.00 ?	
5 FRONT SPOILER <i>scr</i>		\$	379.00 ?	\$303-20
6 FRONT BUMPER AIR GUIDE GRILLE - RH <i>lit</i>		\$	151.00 ✓	\$120-80
7 FRONT BUMPER GUIDE SECTION - RH <i>imp</i>		\$	38.00 ✓	\$30-16
8 FRONT FENDER - RH <i>Distorted</i>		\$	1,271.00 ✓	\$1016-80
9 FRONT FENDER ATTACHMENT PARTS <i>X NN</i>		\$	62.00 ?	
10 FRONT FENDER BRACE - RH <i>Best</i>		\$	87.00 ✓	\$68-96
11 FRONT FENDER BRACKET - RH <i>Best</i>		\$	31.00 ✓	\$24-56
12 FRONT FENDER DAMPING - RH UPPER <i>X NN</i>		\$	31.00 ?	
13 DAMPING SEAL <i>X NN</i>		\$	36.00 ?	
14 FRONT FENDER CLOSING ELEMENT - RH <i>X NN</i>		\$	33.00 ?	
15 FRONT FENDER INSULATION - RH <i>X NN</i>		\$	42.00 ?	
16 FRONT WHEEL HOUSING LINER - RH <i>tern</i>		\$	237.00 ✓	\$189-20
17 WHEEL HOUSING LINER ATTACHMENT PARTS <i>X NN</i>		\$	100.00 ?	
18 WHEEL HOUSING LINER COVER - RH <i>X NN</i>		\$	16.00 ?	
19 WHEEL HOUSING LINER CLOSING ELEMENT - RH <i>X NN</i>		\$	19.00 ?	
20 HEADLIGHT MOUNTING - RH <i>46/m CRA</i>		\$	117.00 X	\$93-60
SUB TOTAL SPARE PARTS	:	\$	5,050.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 6727 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 LED HEADLIGHT - RH <i>≠ CRA</i>		\$	5,526.00 ?	\$4420-80
22 LIFT CYLINDER - RH <i>X NN</i>		\$	208.00 ?	
23 FRONT WHEEL COVER - LH / RH <i>LH NEC, RH missing 2</i>		\$	530.00 ✓	\$424-00
24 FRONT DOOR - RH <i>Repair</i>		\$	2,542.00 +	
25 FRONT DOOR OUTER SEAL <i>3 Me an</i>	NEC	\$	164.00 +	
26 FRONT DOOR ATTACHMENT PARTS		\$	155.00 +	
27 FRONT DOOR CATCH <i>3 Me an</i>		\$	119.00 +	
28 FRONT DOOR COVER - RH <i>1 Me an</i>		\$	265.00 +	
29 FRONT ALUMINIUM RIM - RH <i>beam</i>		\$	756.00 +	
30 SUNDRIES <i>X NN</i>		\$	300.00 ?	
TOTAL SPARE PARTS	:	\$	15,615.00	
TOTAL LABOUR CHARGES	:	\$	8,512.00	
GRAND TOTAL	:	\$	24,127.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *17/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT