

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62221033
ATTN: Motor Claim Department


WS Ref: TP CHINA
Claim Type: Third Party
Accident Date: 16/09/2020
TP Veh Reg No: PA6538G

Estimate No: ES2090733/WS
Date: 18 Sep 2020
Policy No:
Veh Reg No: SMQ9412S
Make/Model: TOYOTA TOYOTA
NOAH
Chassis No: ZWR800305629
Engine No:
Reg. Date: 26/07/2018

Estimate Repair Cost to Vehicle No :SMQ9412S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR TAILGATE	650.00	1 PC	650.00	
2 REAR TAILGATE EMBLEM - HYBRID	35.00	1 PC	35.00	
3 REAR TAILGATE OUTER CHROME MOULDING	310.00	1 PC	310.00	
4 REAR WINDSCREEN GLASS	650.00	1 PC	650.00	
			1,645.00	1,645.00
Special Net				
5 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	
			40.00	40.00
Labour				
6 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	
7 TO REMOVE AND REFIX TAILGATE, LOCY ASSY, REAR WIPER ASSY AND RE-ALIGN THE SAME	400.00	1 LA	400.00	
8 TO REMVOE AND REFIX REVERSE CAMERA AND RESET SYSTEM	50.00	1 LA	50.00	
9 TO PUTTY AND RESPRAY ON TAILGATE	400.00	1 LA	400.00	
10 RUSTPROOFING	30.00	1 LA	30.00	
			980.00	980.00
			Total	S\$ 2,665.00
			Add GST @ 7%	186.55
			Total Amount Payable	S\$ 2,851.55

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE