

1000 FRT CABIN 102/02 bme

## TRANSIT ENGINEERING

ACCIDENT TIME REPORTED	17:20HRS
ACCIDENT DATE	15-Sep-20
BUS CAPTAIN NAME	MUHAMMAD AIDIL BIN IDRIS
THIRD PARTY CLAIM AGAINST	AIG ASIA PACIFIC INSURANCE PTE. LTD.

BUS REGISTRATION NUMBER	SMB30435
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

1000 FRT

NO.	Part or Item Description	Quantity	Total Cost
1	O/S SIDE PANEL R5 <i>5t ✓</i>	1	\$520.00
2	O/S SIDE PANEL FRAME <i>6t ✓</i>	1	\$640.00
3	PANEL WHEELARCH TRIM <i>repair</i>	1	\$87.00
4	O/S SIDE PANEL R6 <i>repair</i>	1	\$230.00
5	N/S HINGE SIDE FLAP (DHGE-0058-00) ?	1	\$126.80
6	O/S HINGE SIDE FLAP (DHGE-0057-00) ?	1	\$126.80
7	SIKAFLEX BLACK <i>see ✓</i>	2	\$32.00
8			
		7% GST	\$123.38
		PARTS TOTAL COST	\$1,885.98

## 1000

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO DISMANTLE & REPLACE DAMAGED PARTS		975 \$1,950.00
TO PERFORM REPAIR WORKS ON RADIATOR AND RADIATOR BOTTOM		650 \$1,300.00
SPRAY PAINTING		1920 \$3,840.00
	7% GST	\$451.50
LABOUR TOTAL COST		\$6,901.50

SPRAY PAINTING \$640 PER PANEL  
LABOUR CHARGES \$650 PER DAY

# ESTIMATED ACCIDENT REPAIR COST



TRANSIT  
ENGINEERING

## SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

## SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	15/9/2020
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	
BUS TYPE (SD / DD)	SD		
LOSS OF USE COST		\$1,800.00	

SUMMARY	
SECTION NO.	COST
1	\$1,885.98
2	\$6,901.50
3	-
4	\$1,800.00
<b>TOTAL</b>	<b>\$10,587.48</b>

PAGE 2

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL

Hp 900 10068

4 days

18/09/2020 @1140

Resy before paint