

Not Authorised
2/11/20
To height before part. 3 days.

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jimmy Goh KI
CLAIM DEPARTMENT
DID : 66547618
FAX :

Date : 28/10/2020 2900.93

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000120

Accident Date : 14/09/2020

Vehicle No : YQ -1813-D

Make & Model : ISUZU FRR90SUQA-C 5.2 Y (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BUMPER	1360.80	1,712.50
1	FRONT BUMPER BRACKET LH	NS	192.90
1	FRONT BUMPER BRACKET RH	NS	192.90
1	HEADLAMP (LH)	Scn	743.80
1	HEADLAMP LOWER MOULDING LH	11	82.90
1	HEADLAMP (RH)	Scn/n/c	743.80
1	HEADLAMP LOWER MOULDING RH	11	82.90
1	SIGNAL LAMP LH	Scn	287.50
1	SIGNAL LAMP RH	11	287.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2565.80
152
2180.93
720
2900.93

Date : 28/10/2020

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000120

Accident Date : 14/09/2020

Vehicle No : YQ -1813-D

Make & Model : ISUZU FRR90SUQA-C 5.2 Y (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE	1,246.30	X
1	FRONT PANEL	RESTORE	X
1	FRONT PANEL EMBLEM "ISUZU"	275.80	X
1	STEP GARNISH LH	373.90	✓
1	STEP GARNISH REFLECTOR LH	129.60	X
1	STEP GARNISH R/H	373.90	X
1	STEP GARNISH REFLECTOR RH	129.60	X
	Sub Total	6855.80	
	Discount 15% On Parts	(1028.37)	
	<u>Special Nett Item</u>		

Date : 28/10/2020

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000120

Accident Date : 14/09/2020

Vehicle No : YQ -1813-D

Make & Model : ISUZU FRR90SUQA-C 5.2 Y (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT NUMBER PLATE	35.00	✓
1	FRONT PANEL ADVERTISEMENT STICKER	280.00	✓
	Sub Total	315.00	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	800.00	300
	TO APPLY ANTI RUST COATING ON AFFECTED AREAS	80.00	✓
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	20
	TO SPRAY PAINT ON AFFECTED AREAS	800.00	400

Date : 28/10/2020

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000120

Accident Date : 14/09/2020

Vehicle No : YQ -1813-D

Make & Model : ISUZU FRR90SUQA-C 5.2 Y (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1730.00	

7,872.43

Remarks:

SUB TOTAL

GST 7.0 % 551.07

TOTAL 8,423.50

Surveyor's name: _____

Principal's name: **ETHOZ Group Ltd**

Survey Date & Time: _____