



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20010031/Qda3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-09-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7828H	Veh. Inspected	FBJ 1788C	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003397MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	18/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA JUPITER MX	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	MH350C004DK658355	Colour	BLUE	
Odometer	66883	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	PIRELLI	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/08/2020	Inspection Date	18/09/2020	
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		