

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER :

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTMG/TP/2009/004
Policy No:	5069479433-05	Date of Loss:	25/08/2020
Vehicle Reg. No.:	FBJ1788C	Driveable?	yes
Driver Age:	07/01/1957	Third Party Vehicle No.:	SHA7828H
Any Injuries?	yes	Contact No:	92476945
Insured/Claimant:	MD ARIF BIN DJARIDJAN	Driver:	MD ARIF BIN DJARIDJAN

Make/Model:	Yamaha, Jupiter	Vehicle Reg. Date:	23/01/2014
Vehicle Colour:	Blue	Engine Number:	50C658525
Chassis No:	MH350C004DK658355	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - U-TURN
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts		5,074.20
Miscellaneous Items		165.00
Labour		2,590.00
Paintwork Labour		490.00
Towing		0.00
Gross Total(\$\$):		8,319.20
GST 7.00%(\$\$):		582.34
Nett Amount(\$\$):		8,901.54

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER / CRU SCR	155.00	-10.00	139.50 ✓
2	1	FRONT FORK LH / SCR	190.00	-10.00	171.00 ✓
3	1	FRONT FORK RH / SCR	190.00	-10.00	171.00 ✓
4	1	FRONT WHEEL DISC ROTOR RH X NN	170.00	-10.00	153.00 X
5	1	FRONT BRAKE CALIPER RH X NN	230.00	-10.00	207.00 X
6	1	FRONT FAIRING / SCR	380.00	-10.00	342.00 ✓
7	1	FRONT FAIRING SIDE LAMP RH / CRU 105	310.00	-10.00	279.00 ✓
8	1	FRONT FAIRING INNER FAIRING / CRU 185	390.00	-10.00	351.00 ✓
9	1	FRONT FAIRING LOWER FAIRING / CRU	220.00	-10.00	198.00 ✓
10	1	FRONT HEADLAMP / CRU 280	377.00	-10.00	339.30 ✓
11	1	FRONT HEADLAMP FAIRING / SCR	330.00	-10.00	297.00 ✓
12	1	FRONT HEADLAMP BRACKET X NN	55.00	-10.00	49.50 X
13	1	FRONT BRAKE LEVER RH / BT	35.00	-10.00	31.50 ✓
14	1	FRONT BALANCER RH / SCR	12.00	-10.00	10.80 ✓
15	1	FRONT SIDE MIRROR RH / SCR	65.00	-10.00	58.50 ✓
16	1	FRONT STEERING STEM / ANY X	135.00	-10.00	121.50 X
17	1	FRONT STEERING CONE & BEARING / ANY X	95.00	-10.00	85.50 X
18	1	FRONT SIDE FAIRING RH / Mid	380.00	-10.00	342.00 ✓
19	1	FRONT SIDE INNER FAIRING RH / Mus	177.00	-10.00	159.30 ✓
20	1	FRONT SIDE FAIRING LOGO RH / Nec	55.00	-10.00	49.50 ✓
21	1	RADIATOR / CRU	477.00	-10.00	429.30 ✓
22	1	RADIATOR BRACKET / NY	55.00	-10.00	49.50 X
23	1	FRONT LOWER CENTRE COVER / CRU	110.00	-10.00	99.00 ✓
24	1	ENGINE COVER RH / EBR	240.00	-10.00	216.00 ✓
25	1	ENGINE GASKET / Nec	55.00	-10.00	49.50 ✓
26	1	FRONT FOOT BRAKE RH / BT	35.00	-10.00	31.50 ✓
27	1	FRONT SIDE CENTRE GARNISH RH / NY	130.00	-10.00	117.00 X
28	1	REAR FAIRING RH / CRU 150	330.00	-10.00	297.00 ✓
29	1	REAR FAIRING LOGO RH / Nec	55.00	-10.00	49.50 ✓
30	1	REAR FOOT REST RH / SCR	35.00	-10.00	31.50 ✓
31	1	REAR EXHAUST SILENCER CHROME / SCR	165.00	-10.00	148.50 ✓
		PROTECTOR RH			

Total Parts (\$\$) 5,074.20**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	CENTRE BASKET / CRU 50	90.00	0.00	90.00 50
2	1	ENGINE OIL / Nec 50%	75.00	0.00	75.00 37.50 5/2

Sub Total (\$\$) 165.00**Estimates On Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Supply Labour To Overhaul Engine.	1,200.00	0.00	1,200.00 50
2	1	To Remove and Refit, Straighthen and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00 30
3	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00 X
4	1	To Disconnect and Reconnect, Check Electrical	30.00	0.00	30.00 X

Estimates On Labour				
No.	Qty	Particulars	Amount	%Disc After Disc
		wiring Harness Wire, Sockets, Replace Damaged Parts.		
5	1	To Conduct Wheel Balancing	60.00	0.00 60.00 X
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	900.00	0.00 900.00
				250
			Gross Labour Cost (\$\$)	2,590.00

Estimates On Paint Work Labour				
No.	Qty	Particulars	Amount	%Disc After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	0.00 40.00 X
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	450.00	0.00 450.00 X
			Gross Labour Cost (\$\$)	490.00

< END OF ESTIMATES >

Repair day - 3 days

4/5

After paint photo

Sim Pn (Ltk)

16/09/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4/5 \$ 3000

3701
38284