

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JIE SENG ENTERPRISE PTE LTD
5025 ANG MO KIO IND PARK 2
#01-51
SINGAPORE 569528
TEL: 64812065
ATTN:

Estimate No: MC1901417
Date: 17 Sep 2020
Policy No: P2164472
Veh Reg No: GBF3530L
Make/Model: TOYOTA HIACE VAN
TURBO

Your Ref No: GBF3530L
Claim Type: Third Party
Accident Date: 15/09/2020
TP Veh Reg No: SHC1687B

Not Authorized
Running After Paint
\$1419.70

3 days

Estimate Repair Cost to Vehicle No :GBF3530L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 TAILAMP LH	1 PC	306.40	✓
2 TAILAMP LOWER COVER LH	1 PC	93.20	✓
3 REAR BUMPER	1 PC	454.30	x
		853.90	
	Less 25%	213.48	640.43
Special Nett			
4 REAR FENDER COMPANY STICKER	1 PC	300.00	250.00
		300.00	300.00
LABOUR			
5 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	350.00
7 TO SPRAY REAR BUMPER,REAR FENDER LH,TAILAMP LOWER COVER LH.	1 PC	600.00	500.00
		1,140.00	1,140.00
Total			S\$ 2,080.43
Add GST @ 7%			145.63
Total Amount Payable			S\$ 2,226.06

TOTAL: SINGAPORE DOLLAR TWO THOUSAND TWO HUNDRED TWENTY SIX AND CENTS SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

HK Auto Service
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE