## AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC1901417 Your Ref : SHC1687B Date : 28/01/2021

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle GBF3530L and your Insured SHC1687B ON 15/09/2020 13:45 ALONG EAST COAST RD

We refer to the above matter.

Please assess through your Insured's (SHC1687B) report and our Client (GBF3530L) – JIE SENG ENTERPRISE PTE LTD's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following:

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance
- 4) LTA Search

The above vehicle was surveyed by Mr Kenneth from LKK as appointed by MS 1ST CAP on 22/09/2020.

We would quantify our claim as below:-

Cost of Repair : \$1,519.08

Loss Of Use : \$270.00(3 X \$90) Surveyor recommend 3 days

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIB MOTOR COMPANY

5**)** Vac K⊅ Tokustrist Park 2**A** K Autopent - Singupers 588947

Kee Mui Hong

## **Authorization to Act**

1, <u>JIE SENG ENTERTRISE PTE LTD.</u> 5025 AMK IND PL 2 HOI-57 (S) 569528  (Vehicle No) hereby authorize Ah Lim Motor Comparto my claim for the repair cost and / or rental and GBF3530L that was damaged pursuant (date) along East Goard	(address), owner of(IBF3530L ny (the workshop) to act for me in respect / or loss of use (Claim) for my vehicle no to the accident which occurred on								
involving the vehicle no SHC16878	(the accident).								
I further authorize the workshop to settle the abov deem fit and the workshop is further authorized to r of my claim with payment cheque/s made in favour of	eceive the payment further to settlement								
I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle is concerned.									
Dated this day of All Signed by Third party claimant Signed by	OR COMPANY  10 10 A Marketing Strain								
Owner vehicle no:	y the Workshop								
Owner vehicle no:									

Personal Data Protection Act 2012

I/ we acknowledge and consent to Ah Lim Motor Company collecting, using and disclosing and / or processing my/our personal data to Third Party service providers and/or Insurance company my / our personal data for the purpose of processing the claims and related insurance / claim matters.

Owner signature

## AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimme@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S: MS FIRST CAPITAL INSURANCE LTD Claim No: MC1901417 36 ROBINSON ROAD Final No: AL1904364

#16-01 CITY HOUSE Date: 28 Jan 2021 SINGAPORE 068877 Policy No: P2164472 62222311 FAX: 62223542 Veh Reg No: **GBF3530L** 

TEL: 62222311 FAX: 62223542 Veh Reg No: **GBF3530L**ATTN: Motor Claim Department Make/Model: TOYOTA HIACE VAN

TURBO

Your Ref No: GBF3530L Chassis No: JTFHT02P100203619

Claim Type: Third Party TP Ins Co: MS 1ST CAP

Accident Date: 15/09/2020

### Tax Invoice-Final Repair Cost to Vehicle No :GBF3530L

	Description	Quantity	List Price <u>S\$</u>	Amount S\$
	SPARE PARTS		<u>54</u>	<u>υ</u> φ
1	TAILAMP LH	LPC	306.40	
2	TAILAMP LOWER COVER LH	1 PC	93.20	
			399.60	
		Less 25%	99.90	299.70
	Special Nett			
3	REAR FENDER COMPANY STICKER	1 PC	250.00	
			250.00	250.00
	LABOUR			
4	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
5	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	350.00	
6	TO SPRAY REAR BUMPER, REAR FENDER LH, TAILAMP LOWER COVER LH.	1 PC	500.00	
			870.00	870.00
			T . 1	06 1 (10 70

Total S\$ 1,419.70 Add GST @ 7% 99.38

Total Amount Payable S\$ 1,519.08

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED NINETEEN AND CENTS EIGHT ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 22/09/2020

For AH LIM MOTOR COMPANY

AH LIST MOTOR COMPANY
No. 10 Aug Mio Kie Industrial Park 2A
#01-09 AVIX Augustian Single 568047
Tot: 048X 1244 255 Com 8170

E. & O. E. AUTHORISED SIGNATURE

## > Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

16 Sep 2020 / 14:57:11

Receipt Date/Time: 16 Sep 2020 / 14:57:11

# Tax Invoice/Receipt

Receipt No.: ITNET-00000-200916-002585

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.  Result of Insurance Enquiry - SHC1687B As at 15 Sep 2020/13:45:00 Insurance Co: MS FIRST CAPITAL INSUF 1 Insurance Enquiry - SHC1687B Enquiry Fee		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
20200916145616729882		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference		5,15	0.04
	Total Amount Payable			7.45
	Paid By			
	400610XXXXXX7963	eNETS Credit Card	d	7.45
	Total		<b>-</b>	7.45
	Cash Change			7.45
	Tendered Amount			0.00
	Excess Refundable Amount			7.45
	- International Control			0.00

# THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# **Enquire Vehicle's Insurance Particulars**

# Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No. SHC1687B Incident Date/Time 15 Sep 2020 / 13:45:00

Insurance Company Name
MS FIRST CAPITAL INSURANCE LIMITED

Save as PDF

ОК →

Print

AXA INSURANCE PTE LTD 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Centre #01-21 Tel: 1800 8804888 Website:www.axa.com.sg GST Registration Number: 199903512M customer.care@axa.com.so



#### CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 ■ Road Transport Act. 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.

: VCA/P2164472

Account No. : 14890

Coverage

: Comprehensive

Sum Insured

: Market Value At The Time Of Loss

Name of Policy Holder

: JIE SENG ENTERPRISE PTE LTD

Vehicle Registration No. : GBF3530L

Period of Insurance

: From 23/09/2019 To 22/09/2020 (Both Dates Inclusive)

#### PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

#### LIMITATIONS AS TO USE\*

(a) Use in connection with the Policyholder's business(b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business

(c) Use for social, domestic and pleasure purposes

This Policy does not cover

(a) Use for hire or reward or for racing, pace-making, reliability

trial or speed-testing

(b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

(05)

#### EXCESS :

#### Own Damage Excess

: SGD 900.00

An Additional Excess is applicable as follows: \$\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years

old and/or less than one year of driving experience.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOMOHA

on 05/08/2019

#### IMPORTANT .

Prolityholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap.

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

#### > Back to OneMotoring

#### **Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 194Z

Vehicle Details

Vehicle No.: GBF3530L
Vehicle to be Exported: No

Intended Deregistration Date: 15 Sep 2020
Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR MANUAL

Primary Colour: White Manufacturing Year: 2016

Engine No.: 1KD2641732

Chassis No.: JTFHT02P100203619

Maximum Power Output: Open Market Value: \$27,952.00

Original Registration Date: 23 Sep 2016
First Registration Date: 23 Sep 2016

Transfer Count:

Actual ARF Paid: \$1,398.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Sep 2026

COE Category: C - Goods Vehicle & Bus

 COE Period(Years):
 10

 PQP Paid:
 \$42,196.00

 COE Rebate Amount:
 \$25,399.00

Total Rebate Amount: \$25,399.00 \$25,399.00

The information contained herein is correct as at 15 Sep 2020

ОК

ī